

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBB 5455498 Yr Regn: Jan / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toyota Hiace c.c. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 81775 T/Radio: Insured / Std / NI / NAEng/No: 1KD2830744C/No: 5TFH1T02P600246899Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15CR: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bridgestone

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 18/11/22 D.O.A. 23/11/22Survey held at JWG AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Chinc Taping & GBS2151H04/12/20 finish 2/5 4200/- after 4 days of repair (Red 13,328.84, 76%)

Date/Time, File Pass to?

☐ Prel. Report  
☐ Final Report

Date/Time, File Return to?

2) 4/12/20-TypistReport Format: MerimenLump Sum / L.E. (\$) 4200Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$ \_\_\_\_\_)☐ Interview (\$ \_\_\_\_\_)☐ Tech. Invs (\$ \_\_\_\_\_)☐ Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S+RS, SI

Photos

Others

TOTAL

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	986K
Vehicle Details	
Vehicle No.:	GBB5549S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Nov 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 4DR AT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2830744
Chassis No.:	JTFHT02P600246899
Maximum Power Output:	-
Open Market Value:	\$29,255.00
Original Registration Date:	15 Jan 2019
First Registration Date:	15 Jan 2019
Transfer Count:	1
Actual ARF Paid:	\$1,463.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jan 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$23,257.00
COE Rebate Amount:	\$18,605.00
<b>Total Rebate Amount:</b>	<b>\$18,605.00</b>

The information contained herein is correct as at 19 Nov 2020

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad


Advertiser Login

Ways of Selling

New 5 Year COE Renewal Toyota Wish 1.8A



2.5% p.a. 0 Down, NO Admin,  
monthly from \$688. 2 Year  
Warranty - Engine, Gearbox  
GV Credit Pte Ltd Star4g



Browse by Category

Sort by Date Posted









20 results/page

19 vehicles

Toyota Hiace

Advanced Search



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	<b>Toyota Hiace</b>	Any	Any	<b>2019</b>	Any	Any	Any	<b>Available</b>
	<b>Toyota Hiace 3.0M</b> <b>Fuel Type:</b> Diesel Under Agent Warranty! Cheaper Depre Than New Unit! Come With Wooden Floor Board.Fast Handover.IFlexible Loan Schemes With Fast Approvals & Immediate Handover! Highest Trade In Quotations Given! WhatsApp / Call Our Friendly Sales Consultant To View This Pow... Car (S) Pte Ltd Posted: 11-Nov-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace	<b>\$62,800</b>	<b>\$7,730 /yr</b>	<b>02-Jan-2019</b>	<b>2,982 cc</b>	<b>36,800 km</b>	<b>Van</b>	<b>Available</b>
	<b>Toyota Hiace 3.0A</b> <b>Fuel Type:</b> Diesel Hiace Van Turbo 4 Door At (Toyota) Year Of Manufacture: 2018 Primary Colour: Black Passenger Capacity: 11 Propellant/Emission Standard: Diesel/ Jpn 2009+Euro V1 Pn Limit Engine Capacity (Cc): 2982 Unladen Weight (Kg): 1960 Maximum Laden Weight (Kg): 280... Posted: 04-Nov-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace	<b>\$71,999</b>	<b>\$8,840 /yr</b>	<b>11-Jan-2019</b>	<b>2,982 cc</b>	<b>50,000 km</b>	<b>Bus</b>	<b>Available</b>
	<b>Toyota Hiace 3.0M</b> <b>Fuel Type:</b> Diesel <b>Auction Closing Time:</b> 25th Nov 2020 at 11:00 PM GST Registered. 3 Keys Available. Road Tax Expiry On 21/01/2021. Mileage Of 75378Km. Toyota Hiace Van Turbo 5DR MT, Maximum Laden Weight: 2800 Kg. Financing Up To 90% Possible Subject To Credit Approval. Call Us To Enquire, No Viewing Of The Vehicle At Th... Posted: 19-Nov-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace	-	<b>N.A</b>	<b>22-Jan-2019</b>	<b>2,982 cc</b>	<b>75,378 km</b>	<b>Van</b>	<b>Available</b>
	<b>Toyota Hiace 3.0A</b> <b>Fuel Type:</b> Diesel Most Reliable Van Toyota Hiace, Well Known For Low Maintenance. Suitable For Business That Needs To Transport Staff Or Students. Unit Is Fully Ready On Road, Even Come With Necessary Item (First-aid Kit And Fire Extinguisher) One Call To Find The Most Suitable Vehicle... Posted: 04-Nov-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace	<b>\$71,000</b>	<b>\$8,620 /yr</b>	<b>14-Feb-2019</b>	<b>2,982 cc</b>	-	<b>Bus</b>	<b>Available</b>
	<b>Toyota Hiace (For Lease)</b> \$1,200/mth Toyota Hiace For Lease! Best Condition You Can Find! Please Call Mike 91158182 For More Information! More info about this vehicle							
	<b>Toyota Hiace Commuter 3.0A</b> <b>Fuel Type:</b> Diesel 14 Seater Euro 6 Mini Bus For Sales! Ready Stock, 3 Years Or 100,000 Km Warranty Whichever Come First, Include 6 Months Road Tax, And Lots Of Accessories, High Loan And High Trade In. Can Register Excursion, Private Hire, Or Private Bus, Call Our Friendly Sales Exec... KSL Automotive Pte Ltd Posted: 09-Oct-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace	<b>\$81,000</b>	<b>\$9,830 /yr</b>	<b>15-Feb-2019</b>	<b>2,982 cc</b>	-	<b>Bus</b>	<b>Available</b>
	<b>Toyota Hiace 3.0M</b> <b>Fuel Type:</b> Diesel 1 Owner! Full Borneo Motor Agent Maintained! Owner Underutilized This Vehicle That'S Why So Low Mileage. Cheapest In Market Yet Drive Like New Vehicle. Toyota Sell By Its Name No Further Explanation! Super Low Mthly At \$855. Trade In And Scrap Welcome. Call/M... Car (S) Pte Ltd Posted: 17-Nov-2020 Tags: 2019 Toyota Hiace, Toyota Hiace, Toyota, Hiace	<b>\$64,800</b>	<b>\$7,810 /yr</b>	<b>06-Mar-2019</b>	<b>2,982 cc</b>	<b>43,159 km</b>	<b>Van</b>	<b>Available</b>
	<b>Toyota Hiace 3.0M</b> <b>Fuel Type:</b> Diesel	<b>\$64,800</b>	<b>\$7,770 /yr</b>	<b>21-Mar-2019</b>	<b>2,982 cc</b>	-	<b>Van</b>	<b>Available</b>

Compare

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/11/2020 12:01
Date Of Accident	18/11/2020 19:15
Exact Location Of Accident	CTE TWRDS SLE BEFORE ANG MO KIO AVE 1 EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB5549S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ROOFWERKZ PRIVATE LIMITED
Co Reg No	2XXXXX986K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98187282
Alternative Phone No	OFFICE-98187282
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	TOYOTA / HIACE VAN TURBO 4DR AT
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5107058458-01
Cover Note Number	

### Driver

Name of Driver	LIM CHEE YONG
NRIC No	SXXXX080A
Date Of Birth	27/10/1965
Occupation	OUTDOOR
Date Of Driving Pass	01/01/1999
Driving Experience	21 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98187282
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	17 NAMLY DRIVE
Postcode	267431
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED;

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ2151H
Vehicle Make/Model/Colour	TOYOTA / DYNA 3.0 MANUAL
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	90050295
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GV8632A
-----------------------------	---------

Vehicle Make/Model/Colour	NISSAN / CABSTAR
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SKH1019T
Vehicle Make/Model/Colour	B.M.W. / 520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4 #02-02  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: vackb@vacom.com.sg

Reporting Centre Personnel's Signature  
Name: **19 NOV 2020**  
NRIC/FIN No.

# Accident Sketch Plan

SKETCH PLAN

CTE TOWARD ANG MO KIO BEGARE PARK AVE1



VEHICLE A = 7G8B5549S

VEHICLE B = 7G8B52151H

VEHICLE C = 7G8V8632A

VEHICLE D = 7SKH1019T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED DATE AND TIME, I WAS TRAVELLING ON THE  
STATED VENUE. SUDDENLY I FELT AN IMPACT COMING FROM THE REAR  
AND I ALIGHTED AND REALIZED I AM INVOLVED IN A CHAIN COLLISION  
OF 4 VEHICLE I MAY CONSULT A DOCTOR TOMORROW

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time



Driver's Signature  
(If driver is not the policyholder)  
Date & Time

IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4 #02-02  
Singapore 415933  
Tel: 67416697 Fax: 67492305  
Email: vacbk@vicom.com.sg

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: 19 NOV 2020



# JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6484 1922

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING GBJ2151H [YOUR INSURED] & GBB5549S [OUR CLIENT]  
ON 18/11/2020.

## ESTIMATED REPAIR COSTS FOR GBB5549S

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE <i>Dented</i>	\$ 1,850.39	✓
1PC	TAILGATE LOGO <i>Hec</i>	\$ 65.29	✓
1PC	TAILGATE INNER BOARD <i>HH</i>	\$ 441.92	X
1SET	TAILGATE INNER BOARD CLIPS <i>HH</i>	\$ 20.00	X
1PC	TAILGATE INNER BOARD HANDLE <i>HH</i>	\$ 197.00	X
1PC	TAILGATE CENTER MOULDING <i>cut / inner broken</i>	\$ 198.00	✓
1SET	TAILGATE CENTER MOULDING CLIPS <i>HH</i>	\$ 20.00	X
1PC	TAILGATE WEATHER STRIP <i>HH</i>	\$ 395.00	X
1PC	TAILGATE INNER LOCK <i>34</i> <span style="float: right;">249.60</span>	\$ 340.00	✓
1PC	TAILGATE LOWER LOCK <i>HH</i>	\$ 105.00	X
1PC	TAILGATE WINDSCREEN MOULDING <i>Hec</i>	\$ 288.21	✓
2PC	TAILGATE NUMBER PLATE LAMP L+R <i>HH</i>	\$ 118.00	X
1PC	TAILGATE THIRD BRAKE LAMP <i>HH</i>	\$ 385.00	X
2PC	TAIL LAMP L+R @ \$482.39 EACH <i>o/s crack H/S HH</i> <span style="float: right;">385.50</span>	\$ 964.78	✓
1SET	TAIL LAMP CLIPS <i>HH</i>	\$ 20.00	X
2PC	TAIL LAMP PANEL L+R @ \$589.20 EACH <i>HH</i>	\$ 1,178.40	X
2PC	TAIL LAMP LOWER GARNISH L+R @ \$239.80 EACH <i>HH</i>	\$ 479.60	X
2PC	TAIL LAMP LOWER GARNISH BRACKET L+R @ \$105.28 EACH <i>HH</i>	\$ 210.56	X
1PC	REAR BUMPER <i>distorted</i> <span style="float: right;">498.50 498.50</span>	\$ 612.00	✓
1SET	REAR BUMPER CLIPS <i>HH</i>	\$ 20.00	X
1PC	REAR BUMPER CENTER BEAM <i>HH</i>	\$ 398.00	X
2PC	REAR BUMPER SIDE RETAINER L+R @ \$58.29 EACH <i>HH</i>	\$ 116.58	X
1PC	REAR END PANEL INNER <i>HH</i>	\$ 933.00	X
1PC	REAR END PANEL OUTER <i>Dented</i> <span style="float: right;">691.25</span>	\$ 982.00	✓
1PC	REAR FLOOR PANEL EXTENSION <i>HH</i>	\$ 1,892.39	X
1PC	REAR FLOOR PANEL TOP BOARD <i>HH</i>	\$ 1,419.00	X
1PC	REAR FLOOR PANEL MAT <i>HH</i>	\$ 1,359.00	X
1PC	REAR SPARE TYRE HOLDER BRACKET <i>HH</i>	\$ 380.00	X
1PC	REAR SPARE TYRE HOLDER BOLT <i>HH</i>	\$ 60.00	X
1PC	REAR EXHAUST PIPE <i>HH</i>	\$ 1,410.00	X

1PC	REAR EXHAUST MOUNTING <i>HH</i>	\$ 116.00	X
1PC	REAR EXHAUST BRACKET <i>HH</i>	\$ 90.00	X

4226.74  
3170.05

PARTS SUM: \$ 17,065.12  
PARTS LESS 25%: \$ 4,266.28  
PARTS TOTAL: \$ 12,798.84

### LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE	\$ 160.00	<i>HH</i>
*	TO SUPPLY REVERSE CAMERA	\$ 600.00	<i>HH</i>
*	TO SUPPLY REVERSE SENSOR	\$ <del>300.00</del>	<i>220/-</i>
*	TO SUPPLY TAILGATE WINDSCREEN SEALANT	\$ 80.00	<i>40/-</i>
*	TO SUPPLY TAILGATE WINDSCREEN DAMPING SEAL	\$ 30.00	<i>HH</i>
*	TO SUPPLY TAIL LAMP PANEL SEALANT	\$ 160.00	<i>HH</i>
*	TO SUPPLY REAR END PANEL SEALANT	\$ <del>150.00</del>	<i>40/-</i>
*	TO SUPPLY REAR FLOOR PANEL INSULATION SEAL	\$ 250.00	<i>HH</i>
*	TO SUPPLY 'TOYOTA' STICKER <i>HH</i>	\$ <del>100.00</del>	<i>15/-</i>
*	TO SUPPLY 'HIACE' STICKER <i>HH</i>	\$ 100.00	<i>20/-</i>
*	TO SUPPLY '70KM' STICKER <i>HH</i>	\$ 100.00	<i>30/-</i>
*	TO SUPPLY '8PAX' STICKER <i>HH</i>	\$ 100.00	<i>30/-</i>
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ <del>300.00</del>	<i>120/-</i>
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ <del>1,600.00</del>	<i>700/-</i>
*	TO RESPRAY NEW PAINTWORK ALL DAMAGED AREAS	\$ <del>1,600.00</del>	<i>600/-</i>
*	TO TUFF COAT AFFECTED AREAS	\$ 250.00	<i>40/-</i>
*	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	\$ <del>300.00</del>	<i>120/-</i>
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ <del>200.00</del>	<i>60/-</i>
*	TO RNR REAR BUMPER REVERSE SENSOR TO FACILITATE REPAIRS	\$ <del>80.00</del>	<i>40/-</i>
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	<i>30/-</i>
*	TO RNR EXHAUST & ATTACHEMENT PARTS TO FACILITATE REPAIRS	\$ 200.00	<i>HH</i>

LABOUR & S/N TOTAL: \$ 4,730.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 17,528.84

23/11/2020 e 1700m  
NA Andreu

5275.05

1/5 4200/-

2/5mm 4 days.

*Juan*

2/5mm Andreu

Check part prices.

We Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: