

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL	R	ef:	CS/SMO20012832/T1Kqf3n2	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	D	ate:	15/07/2021	
			C	ode:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLT 9622Z	Veh. Inspected		SKH 1132Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2003381/RUC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		23/11/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	AUDI A3 SB 1.0	c.c		999	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	WAUZZZ8V7HA032108	Colour		WHITE	
	Odometer	73868 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	GOODYEAR		6 mm	
	L/H Front Tyre	205/55 R16	GOODYEAR		6 mm	
	R/H Rear Tyre	205/55 R16	GOODYEAR		6 mm	
	L/H Rear Tyre	205/55 R16	GOODYEAR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	18/11/2020	Inspection Date		23/11/2020	
	Survey held at	MOVA AUTOMOTIVE PTE LTD				
		BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 . SINGAPORE 159722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days					
	LOTIMATED NOR	VIAL I ENIOD I ON INEI AIIN.		TTOIRI	ng Days	