

08/11/13 wef
ASS. REC. BY: Marcus

REF: CCG/CT/20012855/4es3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJX 8814X
at Workshop m/s RL
of _____
Insured: SMY 8071C
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 626k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

643F
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJX 8814X Yr Regn: 21/7/10
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: KIA Cerato Ex forte c.c 1591
Colour Blue A/C: Insured / Std / NI / NA
Sp. Reading 160611 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KNAFU 411MA5199394
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Good / Jammed / Leaked / Burnt or
Brake: Good / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: 215/45ZR17

BS / DUN / EXNOVA / GY / FS / EIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front R/Bal. 9 mm L/Bal. 9 mm
D.O.A. 20/11/20
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Body 2
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COE 20-7-2025 + TA #15308
new tyres. NetH 10692

29/12/20 4/5 @ 7000 confirmed with Alan.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS, SI

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

Lim. Asher

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

VEHICLE No: SJX 8814X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
New
23/11/20
1/s 7000
5 days

1PC	FRONT DOOR O/S	Bodily PD / Sent
2PCS	FRONT DOOR HINGES @ \$90.00	11
1PC	FRONT DOOR CHECKER O/S	11
1PC	FRONT DOOR OUTER HANDLE O/S	11
1PC	FRONT DOOR GLASS OUTER MOULDING O/S	11
1PC	FRONT DOOR GLASS REGULATOR & MOTOR O/S	shorted / Jm
1PC	FRONT DOOR INNER LOCK O/S	shorted
1PC	FRONT DOOR INNER TRIM BOARD O/S	De / Crea
1SET	FRONT DOOR FRAME BLACK STICKER O/S	11
1PC	REAR DOOR O/S	Bodily PD / Sent
2PCS	REAR DOOR HINGES @ \$90.00	11
1PC	REAR DOOR CHECKER O/S	11
1PC	REAR DOOR GLASS OUTER MOULDING O/S	11
1PC	REAR DOOR GLASS REGULATOR & MOTOR O/S	shorted / Jm
1PC	REAR DOOR INNER LOCK O/S	shorted
1PC	REAR DOOR INNER TRIM BOARD O/S	De / Crea
1SET	REAR DOOR FRAME BLACK STICKER O/S	11
1PC	REAR FENDER O/S	R
1PC	REAR SHOCK ABSORBER O/S	11
1PC	REAR WHEEL HUB BEARING O/S	Damaged
1PC	REAR AXLE BEAM ASSY	Bent / Twi
1PC	REAR BUMPER	R
1PC	ROCKER PANEL GARNISH O/S	R

\$1,205.00	✓	980.00
\$180.00	X	
\$145.00	X	
\$220.00	X	
\$122.00	✓	82.00
\$605.00	✓	450.00
\$399.00	✓	250.00
\$650.00	✓	480.00
\$80.00	✓	60.00
\$1,105.00	✓	955.00
\$180.00	X	
\$145.00	X	
\$115.00	✓	80.00
\$585.00	✓	450.00
\$399.00	✓	250.00
\$645.00	✓	455.00
\$80.00	✓	60.00
\$1,215.00	X	
\$388.00	X	
\$485.00	✓	355.00
\$1,450.00	✓	1250.00
\$820.00	X	
\$845.00	X	
\$12,603.00		

S.NETT

1SET	ROCKER PANEL GARNISH CLIPS	11
1PC	REAR SPORT RIM O/S	Cru
1PC	REAR TYRE O/S	cut 2P 200
1SET	REAR TYRE 'MICHELIN' FOAM O/S	11
1SET	FRONT DOOR & REAR DOOR VISOR O/S	11

5/11

\$50.00	✓
\$680.00	500
\$480.00	90% = 180
\$150.00	80
\$150.00	100

TO CHECK WIRING	\$80.00	20
TO TRANSFER BOTH DOOR MECHANISM	\$120.00	100
TO CONDUCT WHEEL ALIGNMENT	\$150.00	80
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$400.00	300
TO SPRAY RUST PROOFING	\$880.00	60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,500.00	580
TO PUTTY & SPRAY PAINTING	\$1,500.00	1180

TOTAL \$18,743.00

2-6157 8771-3
100 7017
5541.00