

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG20012866/R1TD3E2

**Date:** 01/12/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001212937

**Claimant Vehicle No :** SGN8801X

**Insured Vehicle No :** SKU6934A

Date of Loss: 07/11/2020

Nature of Claim: TP

Claim No: 249584

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGN8801X**

Make & Model: CITROEN GRAND C4 PICASSO, 1.6 BLUEHDI EAT6 (A)

Engine No: 10JBHD3049789

Reg. Date: 21/07/2016 (Man. Year: 2016)

Chassis No: VF73ABHZTGJ643185

Colour: Brown

Odometer: 42616 km

Engine Capacity: 1560 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R15

Rear Tyre Size: 205/60 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 24/11/2020

Date Inspected: 24/11/2020 Inspected At:

Han Car Repairs (HQ)  
BLK 1001 BUKIT MERAH LANE 3 #01-49  
ALEXANDRA VILLAGE  
Singapore 159718

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 01 Dec 2020)	
<b>Parts:</b>	N/A	CITROEN GRAND C4 PICASSO 1.6 BLUEHDI EAT6 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGN8801X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**