

ASS. REC. BY:

REF: CS3/MSG20012866/R1td3

Special Instruction:

Surveyor: RASULASSIGNMENT (Office)From (Person): CRSTAL LEE of MSIG Date/Time: 23/11/2020 2:39 PM

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGN 8801X Insured: SKU 6934Aat Workshop m/s Han Car Repairs Tel: 9777 7266of 1001 Bukit Merah Lane 3 #01-49, Alexandra Village

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07-11-2020
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 23-11-20 2.57P.M Person Contacted: SUSAN Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SGN 8801X- NA/MSG20012252/h4 DOA :07/11/2020
	SKU 6934A- NA/MSG20012252/h4 DOA :07/11/2020