

NAZ

REF:

INDIA

ASSIGNMENT

File No: _____ Date: _____

Insured Class:

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Excess: _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

Insured Vehicle No. _____

25K

Insured Vehicle No. _____

Condition? Yes or No

Insured Vehicle No. _____

Condition? Yes or No

Insured Vehicle No. _____

4

days

Rest? Yes or No

Insured Vehicle No. _____

3

Valid? Yes or No

Insured Vehicle No. _____

Vehicle W/OUT

Insured Vehicle No. _____

Person Contained

Insured Vehicle No. _____

Action/Instruction

COE Rebate : \$3,422.00

Repair Limit : \$20K Repairer informed and agreed

Veh No. _____

FBI 969D

Yr Regn

27 NOV 2019

Type: M. Car / M. Cycle / BUS / Van / Lorry / Taxi / Private Motor /

Truck / Trolley or

Make:

HONDA ADV 750

cc 745

Colour

GREY

AC: Insured / Not Insured

Sp. Reading

35,072

TR: Insured / Not Insured

Engine

Chassis

JH2RC9SA3KK205878

Gen. Cond. Good / Fair / Poor / Burnt

Steering: (order) / Jammed / Locked / Burnt or

Brake: (order) / Jammed / Leaked / Burnt or

Wheels: (all) / (left) / (right) / (front) / (rear) or

Tyre Size: R:

120/70R17

R:

160/60 R15

BS / COM / EX / NOVA / GY / PS / LZA / MC / COM / SU / PR / SU /

GYO / YOKO or

Front

Width

3

mm

Rear

Width

3

UBS

mm

UBS

DDA

15/11/2020

DDA

24/11/2020

Survey held at

BIKE REPAIRER

Gen. of Damages: (Frt) / (Rear) / (O/S) / (N/S) / (U/C) / (Rock) or

The UIC / Chassis frame / Body Structure affected due to

4/5

Days of Repair:

Pre-Report

Report

Days of Repair:

Pre-Report

Report

Days of Repair:

Pre-Report

Report

Days of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

Site Insp

15

Interview

15

Techn. Invs

15

Workshop

15