

ASS. REC. BY:

REF:

CC3/111 20019907/bs3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLU 207T Yr Regn: 21/11/17Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 216 c.c. 1499Colour: Black A/C: Insured / Std / NI / NSp. Reading: 62779 T/Radio: Insured / Std / NI / N

Eng/No: _____

C/No: WDA2092035 E91648Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: N11 / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 20/11/20 D.O.I. 4/12/20Survey held at Performance MotorDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-96K

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Inve (\$ _____)☐ : Weekend (\$ _____)

Rep. Form:

Lump Sum / L.E. / C

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	658E
Vehicle Details	
Vehicle No.:	SLU207T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2020
Vehicle Make:	B.M.W.
Vehicle Model:	216I GT LED
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	34645116B38A15A
Chassis No.:	WBA2D920305E91648
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$28,741.00
Original Registration Date:	21 Nov 2017
First Registration Date:	21 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$32,238.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2027
PARF Rebate Amount:	\$24,178.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,112.00
COE Rebate Amount:	\$32,795.00
Total Rebate Amount:	\$56,973.00

The information contained herein is correct as at 04 Dec 2020

OK