

						CO	ENGINEERING
Our Job Ref No : 305435054							
Date : 30/11/20					ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969		
FINA	ALIZAT	ION FORM				Fax	c: 6546 8156
То	:		LKK			Fax :	
Attn		10-	STEVE				
Vehi	cle Reg	No. : SHC	8905B		21/11/2020		
The	survey	and estimates of	the repairs of the above-	-mentione	d vehicle	e are as follow	/s:-
Z		repair job shall bil	TOKIO			GBG6782B	
2.	The finalized amount shall be:						
	(a) Spare Parts after List discount						
	(b)	Labour Charges					<u> </u>
	(5)	_	3y-Part Repair Cost				41
	(c.)	•	air (if applicable)				
		Final Lumpsur	um repair cost after Less n Repair cost	5.		<b>=</b> 1	\$1,800.00
							.,
3. 4.	Estimated normal period for repairs: 2 working days.  We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days						
5.	Than	k you for your ass	sistance.	We confirm the finalized amoun			t
	Signs	iture :	1/1/			gnature:	
	Name	8	00			ame :	Steve
Tel : 621483			1		Da		1/12/20
	Fax						1112/20
For C	Official	Use Only					
		Item	Amount	A1	cument tached s or No	Confirm By (Signature)	Remarks
l. Re	ental R	ate P/Day			YES		
2. Lo	ss of I	ncome Paid			N		
3. Survey Fees							
LTA Search Fee     Medical Fees (on behalf of driver, if applicable)			\$7.49/\$2.00	20			1
6 Ov	/errun						
Rema	ırks:						