

ASS. REC. BY: Tan Jiah

REF: Ce4/FCI 20012918/T. es3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$64K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: me/wn

Veh No: SJG 6283A Yr Regn: 2018 March

Type: M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hardy Shuttle c.c. 1496

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 49586 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GK 81201726

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 24/11/20

Survey held at Wah Thong

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L&L: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	561H
Vehicle Details	
Vehicle No.:	SJG6383A
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2020
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	L15B5462012
Chassis No.:	GK81201726
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$19,387.00
Original Registration Date:	29 Mar 2018
First Registration Date:	29 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$9,387.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2028
PARF Rebate Amount:	\$7,040.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$27,927.00
Total Rebate Amount:	\$34,967.00

The information contained herein is correct as at 21 Nov 2020

OK