

CS3/AIG20000667/Etd3-1

ASS. REC. BY:

REF: ~~CS3/AIG20000667/Etd3-1~~

Investigator: Steve

meimich ANGIEGEOKLING

ASSIGNMENT (Office)

24/11/2020

From (Person): ~~Wong Jee~~

of AIG

Date/Time: ~~12/11/2020 2:16pm~~

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 8331E

Insured:

SLB 9018M

at Workshop n/s:

Wee Hye Auto

Tel:

6858 0019

of

19 Kim chuan terrace

Policy No:

Claim No:

160083972556

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/10/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:50pm 10/1/2020

Person Contacted:

Kiat

Vehicle: IN/OUT

Date/Time	Action/Instruction	Initials
	SLR 8331E - CC4 / JCR 1800344 / Kha 292	
	SLB 9018M - X	
	Request TP GIA from WHP.	
	Submit DAR Report	

Birruyar

Steve


REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OO / TP / WS / TP-RES / OD-RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/c \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLR 8331E Yr Regn: 29/8/17  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Tractor or  
 Make: Honda Vezel c.c. 1496  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 1043.73 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/N: R43-1253177  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brakes: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / SRim / STD A/Rim or  
 Tyre Size: F: 215/69R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or



(Policy Condition)  
 Remark: The veh. had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 7/1/20 D.O.I. 10/1/20  
 Survey held at Wae Hoe Auto  
 Des. of Damages: Frnt / Rear / O/S / NIS / UIC / Rooftop or

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/1/20	No GIA report (pending) MV - 73K Repair range 7-8K 9 days

RECEIVED 30 JAN 2020

Date/Time, File Pass to?  : Provl. Report  
 11:30 AM Typist  : Final Report  
 Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:	180
Transportation:	
Other:	11
TOTAL	191

Report Format: TP-DAR  
 Lump Sum / I.B.I: (\$)

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Insp (\$)  
 : Weekend (\$)