Surveyor Steve | REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP-RES / OD-RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SLR 8331E Yr Regn: 29/8/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Texi / Prime Mover / Truck / Trailer or

Make: Honda Vezel c.c 1496

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 104373 T/Radio: Insured / Std / NI / NA

Eng/No:

Ch/No: RU3-1253177

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	5 mm	R/Bal.	5 mm
L/Bal.	5 mm	L/Bal.	5 mm
D.O.A.	7/1/20	D.O.I.	10/1/20

Survey held at Wee Hoe Auto

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/1/20	No GIA report (pending)
	MV-73K
	Repair range 7-8K
	9 days

5350;red6760;55%

lump sum 6350; red:5760;47%)

RECEIVED 6 JAN 2020

Date/Time, File Pass to? 11/3/20 Typist

Date/Time, File Return to?

☐ : Proll. Report

☑ : Final Report

Days Of Repair: 8

Resurvey No. of Trip:

Survey Fee: 180

Transportation:

Photos:

Others:

TOTAL 191

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : TP-DAR

Lump Sum / I.B.I: ($)