REF: Smo/ 20012939/K+ ASS REC. BY: ASSIGNMENT Tenneth FBL 827/M Yr Regn: 03,17 Date: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Estimated Cost: Truck / Trailer or OD THE WS ITP RES I OD RES I EVA I INV I MY To Inspect Vehicle No: Colour at Workshop m/s T/Radio: Insured / Std / N1 / NA Sp.Reading Eng/No: Insured: ML986381000 056614 Policy No. Gen. Cond: Good | Fair | Poor | Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: NII / S/RIM / STO A/RIM or Make of Veh: 801PORIG Tyre Size: 130/701213 (Policy Condition) N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI / Remark: The veh had commenced Its repair at the time of inspection. TOYO / YOKO or Front Rear Bal. or Market Value: R/Ba! R/Bal. Consistent?: Yes or No IDAC Accident Rport: L/Bal. Consistent?: Yes or No GIA / PR Scent D.O.A. 28/9/20 Res.: Yes or No Est. Repairs: 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision Date / Time Action / Instruction 24/12 8/1/mp 8 24501 Cersone : Prell. Report Days Of Repair: : Final Report Resurvey No. of Trip: Survey Fee: Transportations Add Fee: : Site Insp (\$ S - RS. SI Interview (\$ Report Format: Tech Invs (\$ 1 Others Lump Sum / I.B.I: (S Weekend (\$

MITAL









Block 32, Sin Ming Drive, #01-331, Singapore 575706 TEL::4539903,4539904 FAX::4539904

Importer & Exporter - New & Used Motorcycles. Spare Parts & Accessories. Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.



Date: 21-11-2020

Estimated repair list for the accident motorcycle Yamaha Triciity 155 Vehicle no. FBL9271M

Latini	ated repair list for the accident mo	torcycle rama	an income the control of the control	L55 Vehici	e no. FBL927
1 pc	Windshield		ndl la	\$120.00	
1 pc	Front Cover		SL	\$180.00	X
1 pc	Front side fairing (L)		mycm	\$320.00	2
1 pc	Front side plastic cover (L)		nallon	\$150.00	
1 pc	inner side cover (L)		cm	\$225.00	
1 pc	Handle bar			\$130.00	
1 set	Handle balancer			\$50.00	_
1.pc	Brake lever (L)		nu	\$75.00	
2 pc	Front fork inner tube(L)		Dilla	\$420.00	2
1 set	Fork oil seal & fork oil		New	\$70.00	Solin
1 pc	Front mudguard (L)		nullan	\$180.00	
1 pc	Fender plastic cover		w	\$110.00	
1 pc	Head light		Sin	\$380.00	X
1 pc	Signal light (L)		CM	\$200.00	
1 pc	Mirror (L)		nu		
1 pc	Bottom cover (L)		In	\$230.00	X
1 pc	Floor board		SL	\$250.00	X
1 pc	bottom side board		cm	\$280.00	1
1 pc	Belting cover		pallor	\$265.00	
1 pc	Air cleaner box		nd161	\$350.00	_
1 pc	Box lock	119	Ai	\$25.00	
1 pc	Side board (L)	8	a	\$280.00	7
1 pc	Side stand		R		X
	Towing			\$50.00	301
	Labour			\$350.00	1801
					-01

Total:

\$4865.00

Not Notheries

LISmp & 245 oh

Resurry After Paint

notify

inting

4 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



MVA220084671 / VAC - Sin Ming ENTRY DATE & TIME: 29/09/2020 09:40 SUBMITTED BY: CHRISTINA ONG Mui Lan

## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

<ol><li>By the lodgement of this report to the insurers, you hereby consaforesaid.</li></ol>	ent to the archiving of this report at the c	entre and to copies of the report being made available		
A TOTAL BOOK OF THE STATE OF TH	ACCIDENT STATEMENT	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Date Of Report	29/09/2020 09:40	or Po North		
Date Of Accident	28/09/2020 11:55			
Exact Location Of Accident	32 SIN MING DRIVE #01-323			
Country/State of Loss	SINGAPORE			
THE RESERVE OF THE PARTY OF THE	ETAILS OF OWN VEHICLE	The second second		
Vehicle Registration Number	FBL9271M			
Insured/Policyholder				
Name Of Registered Owner	PAS AUTO PTE LTD			
Co Reg No	2XXXXX120M			
Email Address	NOEMAIL			
Mobile Phone No				
Alternative Phone No	OFFICE-64590882			
Vehicle Particulars				
Manufacturer	YAMAHA			
Model	TRICITY 155 ABS	\$1.5450 (\$1.645), \$1.50 (\$1.50) (\$1.65) (\$1.65)		
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE			
Are you claiming under your own insurance policy for repair to your vehicle?	NO			
If No, Please state action to be taken	THIRD PARTY			
Vehicle Category	MOTORCYCLE			

Vehicle Category

**Insurance Company** 

Name of Insurance Company

Type Of Coverage

Fleet Policy

Policy Number

Cover Note Number

Driver

Name of Driver

NRIC No Date Of Birth

Occupation

Date Of Driving Pass **Driving Experience** 

Gender

Mobile Number Fax Number

Cantant Alimahan

FONG SOON YONG

5091101277-03 (TPFT)

NTUC INCOME INSURANCE CO-OPERATIVE LTD

THIRD PARTY FIRE AND/OR THEFT

GXXXX956P 15/04/1989 OUTDOOR 25/02/2012

MALE

NO

8 YEARS AND 7 MONTHS

(LOCAL) +65-83322344

OTHER 02222244

Address

C/O BLK 32 #01-325 SIN MING DRIVE

Postcode

575706

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance? Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

THOMSON NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 25 SIN MING ROAD, POSTCODE: 570026, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4529999 - FAX NO: 6 5535740

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

REFER TO NOTICE OF REPORTING ATTACHED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

YN6754Z

**Details Of Properties** 

COMMERCIAL VEHICLE

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

SKETCH PLAN	B1k 36	coffee s	hop		
Sin Ming Prive	one way	B			
B1k 32		A			
				7.5	k vý.
ESCRIBE CIRCUMSTANCES OF THE A	ACCIDENT				
				2.0	
V# 5					
ARATION					

Policyholder's Signature

Date & Time:

29 SEP 2020

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Annex D

# NOTICE OF REPORTING

This is to confirm that Fong Soon Yong H/P: 83322344, NRIC/FIN: G6632956P has reported to the Police a non-injury traffic accident which occurred along 32 Sin ming Drive #01-323 on 28/09/2020 at 1155hrs involving the following vehicles:

- A) FBL9271M Complainant's Motorbike
- B) YN6754Z Other party vehicle

On the 28/09/2020 at 1155hrs, my company motorbike (FBL9271M) was parked along 32 Sin Ming Drive infront of unit #01-323. Suddenly, I saw one lorry (YN6754Z) reversing and colliding into my company's motorbike which caused it to fall to the ground. The damages to the motorbike is the front, left and rear portion damaged. There is a box mounted on the rear of the motorbike which was damaged during the collsion. There was no damages seen on the lorry. We decided on insurance claim and left the accident location. I am lodging report for insurance claim.

2. If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

HIGHASON (IPP BLK 25 STR MING (MIND)

302GAPORE 570025 FEL: 1800-4520099

01-50

Rank/Name of Issuing Officer: SGT Cassidy Tan

Date: 28/09/2020 Time: 1735hrs S/D Ref: eSD 36

Police Post/Unit: THOMSON NPP

Original - to be issued to informant Duplicate - to be submitted to Traffic Police