

ASS. REC. BY:

Steve

REF:

AIG 200129651 Ebs3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SH 9647H

Yr Regn:

8/11/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai i30

C.C

1580

Colour:

Blue

A/C: Insured / Std / NI / N

Sp. Reading

287418

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KMHCH851 CVK 115143

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

21/11/20

D.O.I.

24/11/20

Survey held at

Comfort delgro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt R4. 11 Rear

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Rep. Form:

Lump Sum / L.B.:

REPAIR ESTIMATE*

VEHICLE NO SH9647H

DATE 24/11/20

MAKE :

MODEL : HYUNDAI IONIQ G2

/CHIANG /AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER <i>/ B CUT</i>			\$418.30
1	FRONT BUMPER GRILLE RH <i>X NM</i>			\$93.45
1	FRONT DAYLIGHT RH <i>X NM</i>			\$642.50
1	FRONT BUMPER BRACKET RH <i>X NM</i>			\$35.00
1	HEADLAMP ASSY RH <i>X NM</i>			\$1,993.65
1	HEAD SUPPORT PANEL <i>X NM</i>			\$949.30
1	FRONT RH FENDER <i>/ DO</i>			\$588.80
1	FRONT FENDER SHIELD RH <i>X NM</i>			\$164.70
1	FENDER EMBLEM BLUE -DRIVE <i>/ MC</i>			\$26.60
1	FRONT RH WHEEL COVER <i>/ CUT</i>			\$346.40
1	REAR BUMPER COVER <i>X R</i>			\$459.40
1	REAR BUMPER CENTRE MOULDING <i>/ CRU</i>			\$451.25
1	REAR BUMPER REINFORCEMENT <i>X NM</i>			\$394.80
10	REAR BUMPER CLIPS <i>X NM</i>			\$22.00
SUB TOTAL				\$6,586.15
20.00%				\$1,317.23
DISCOUNTED TOTAL				\$5,268.92
1	REVERSE SENSOR <i>X NM</i>			\$180.00
1	REAR NUMBER PLATE W/HOLDER <i>/ BR</i>			\$50.00
				\$230.00
Labour Charge				
Panel Beating FRONT/REAR				\$800.00
Spray painting FRONT/REAR				\$800.00
Check Lighting				\$60.00
Remove/refix reverse sensor				\$60.00
Tuff coating				\$90.00
Remove/refix A/c condenser & charge gas				\$120.00
TOTAL LABOUR				\$1,930.00
ESTIMATE TOTAL				\$7,428.92
<i>Sten (LKK)</i> <i>24/11/20, 4.00p</i> <i>3 dys</i> <i>PIP</i> <i>My Bel sy</i>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.:305435290

CUSTOMER	REGN NO.: SH 9647H	MILEAGE
MR/MS COMFORT TRANSPORTATION PTE LTD	MAKE : HYUNDAI	FUEL E.....1/2.....
CUSTOMER NO. 7010045	MODEL IONIQ(G2)	DATE/TIME IN 21.11.2020 13:15
ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717	YR OF MANU. 08.11.2018	TARGET DATE
TEL. (R) 65508755 (O)	CHASSIS CODE KMHC851CVKU115143	COMPLETION DATE/TIME:
(P)		
DISCOUNT CARD NO.		


JOB DESCRIPTION

Accident Date: 21.11.2020

NATURE: 3P 21.11.2020

S/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

Re:
No.:
Vehicle No.: SH 9647H CHIANG

Vehicle No.: SH 9647H

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard