

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLV 7934B
Vehicle Model : MAZDA 3
Accident Date : 22.11.2020
Original Reg Date : 16.01.2018

Date : 23.11.2020
Chassis : JM6BN24A8J0200941
TP Ins. **FIRST CAP**

ESTIMATE

1	1 pc	Front Bumper			de	967.00
2	2 pcs	Front Bumper Side Retainers	RH X LH	38.00	LH de	76.00
3	1 set	Front Bumper Clips			nei	50.00
4	1 pc	Front Bumper Top Garnish			X ny	175.20
5	1 pc	Front Bumper Reinforcement			? htr	529.50
6	1 pc	Front Bumper Lower Grille			X ny	141.50
7	1 pc	Front Bumper Fog Lamp LED LH			? chr	369.00
8	1 pc	Front Bumper Fog Lamp Cover LH			ant	85.50
9	1 pc	Front Bumper Fog Lamp Chrome LH			? chr	72.00
10	1 pc	Front Grille			? chr	560.00
11	1 pc	Front Grille Badge			? chr	69.00
12	2 pcs	Front Grille Outer Chrome Moulding	RH X LH	149.00	LH - ? chr	298.00
13	1 set	Front Grille Clip			? nei	30.00
14	1 pc	Headlamp (HID) LH			? chr	377.8

5,311.70

Less 20% 1,062.34

4,249.36

Labour charge

Panel Beating		400	900.00
Spray painting		500.	900.00
Check Wiring		30.	40.00
Anti rust		X ny	50.00

6,139.36

Less 20% 1,227.87

Lump sum 4,911.49

Tanpin 97495749
WP' 24/11/2015
Lump sum 04 days
Repair after repair
Tanpin C 11/11/2015

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLV 7934B

Vehicle Model : MAZDA 3

Accident Date : 22.11.2020

Original Reg Date : 16.01.2018

Date : 24.11.2020

Chassis : JM6BN24A8J0200941

TP Ins. **FIRST CAP**

SUPPLEMENTARY

1	1 pc	Front Bumper Signal Lamp LH	327.00	one ✓
2	1 pc	Front Grille Side Garnish LH	68.50	one ✓
			395.50	
			Less 20%	
			79.10	
			316.40	

5357.60

930

316.40

6604

4/5 \$ 5250

4 days \$