




SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/11/2020

User ID : JeongCH

Section A - Accident Details	
Registration Number	SG5870K
Case Reference Number	BUS/11/20/5025
Registration Date	11/16/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	
Type of Accident	Side Swipe
Accident Date and Time	11/17/2020 3:35 PM
Accident Reported Date and Time	11/17/2020 6:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SG5870K-CENTER AND REAR BODY SCRATCHES,CENTER WINDOW PANEL SHATTERED AND RIGHT REAR TAIL LIGHT COVER BROKEN GBG6017C (TP) INSURED WITH INDIA
Prepared Date and Time	11/24/2020 10:42 AM
Chassis Number	WMAA95ZZ8G7003550
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$1,622.00	\$0.00
Total Spare Part Cost	\$4,119.38	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$7,861.38	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date		
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/11/2020

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$2,120.00	
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$1,622.00	
Total Spray Painting & Panel Beating	\$1,622.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	10.00	\$211.50		
6013494	BODY RH	124-2-2-001-026	SIDE PANEL R7	1.00	\$1,115.00	0.00	\$1,115.00		
6013495	BODY RH	124-2-2-001-027	SIDE PANEL R8	1.00	\$657.50	100.00	\$0.00	Replace	
6013496	BODY RH	124-2-2-001-028	SIDE PANEL R9	1.00	\$500.00	100.00	\$0.00	Replace	
6013523	GLASS	124-4-2-001-015	SIDE GLASS R10	1.00	\$641.00	0.00	\$641.00	Replace	
			SMRT STICKERS	1.00	\$35.00	0.00	\$35.00	Replace	
6010298	VE	88-25225-6039	LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	
6010299	VE	88-25320-6008	LAMP,INDICATOR:LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	
4006314	CONSUMABLE		ADHESIVE:DIRECT GLAZING	16.00	\$37.00	0.00	\$592.00	Replace	
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	
Total					\$5,796.30		\$4,928.72		

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									