SLA 6784J
CO 1987

Surveyor: NAZ | REF: AXA

ASSIGNMENT

Date:

Estimated Cost:

TP / TPFT / TP RES / CO RES / EVA / INV / MV

Transferred Vehicle No.:

Transferred to:

Excess:

Veh No: SLA 6784J | Yr Regn: 11 MAR 2016

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA VEZEL 1.5X CUT | cc: 1496

Colour: RED | A/C: Insured / Std / Nil / N/A

Sp Reading: N/A | T/Radio: Insured / Std / Nil / N/A

Engine:

Chas: RU1107590

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Locked / Burnt or

Brake: Inorder / Jammed / Locked / Burnt or

Wheels: Nil / SpRim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: "

BS / DUN / EXHOVA / GY / FS / LIZA / MC / MITSU / PIR / SUN / TOYO / YOKO or

	N/S	O/S

Repair at the time of Inspection

Repair commenced

Estimated Cost: 53K

Repairer Name: Consultant: Yes or No

Consultant: Yes or No

Days: days Res.: Yes or No

Salvage: % Val.: Yes or No

CA / REV / REP / 24 HRS

Vehicle IN / OUT

Parts Collected:

	Front	Rear
R/Bal	- mm	R/Bal -
L/Bal	- mm	L/Bal 4
DOA	21/11/2020	DOA 25/11/2020

Survey Firm: PROGRESSIVE AUTO

Dec. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

entire vehicle burnt

Tyre / U/C / Chassis frame / Body Structure affected due to other

L/S

Date	Action / Instruction
	COE Rebate $30,899.00
	Repair Limit $20,000

Date of Report: ☐ : Prelim Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Inspection:

Add Fee: ☐ : Site Insp $

☐ : Interview $

☐ : Tech. Inv $

☐ : Weekend $

Report Number:

Time Sent: