

ASS. REC. BY:

REF:

CS/AGI 20012987/RIS/3

C  
8014

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX 84755at Workshop m/s THINK ONEof 60, JLN LAM HUAH #02-32 CARLOSInsured: AGI

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 80K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLX 84755 Yr Regn: 2018 / APRType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA MSH 1.8 CVT c.c. 1798Colour: WHITE A/C: Insured / Std / MI / NASp. Reading: 55266 T/Radio: Insured / Std / MI / NA

Eng/No: \_\_\_\_\_

C/No: JTDG420W00J008938Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 23/11/2020 D.O.L. 25/11/2020Survey held at THINK ONEDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

RASUL CONFIRMED L/S \$3,550.00/8 DAYS WITH MICHAEL  
(\$6,715.80/RED - 65%)Date/Time, File Pass to? 17/12/20201) TYPIST

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format:

Lump Sum L.S. (\$) L/S \$3,550.00☐ : Prelt. Report☒ : Final ReportDays Of Repair: 8Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Think One Autocare Pte Ltd  
No.60 Jalan Lam Huat #02-32 Carros Centre  
Singapore 737869

**SLX8475S TOYOTA WISH**

DATE 23.11.2020

No	Qty	DESCRIPTION	AMOUNT S\$
1	1	FRONT BONNET <i>bt</i>	787.00
2	1	FRONT BONNET LOGO <i>rec</i>	115.00
3	1	FRONT BONNET HINGE R <i>bt</i>	85.00
4	1	FRONT BONNET LOCK <i>?</i>	245.00
5	1	RADIATOR GRILLE <i>cm</i>	325.00
6	1	FRONT BUMPER <i>de</i>	335.00
7	2	FRONT BUMPER RETAINER R+L <i>rec</i>	78.50 157.00
8	1	FRONT BUMPER SPONGE <i>?</i>	185.00
9	1	FRONT BUMPER RE-INFORCEMENT <i>?</i>	325.00
10	1	BUMPER RE-INFORCEMENT BRACKET RH <i>?</i>	102.00
11	1	FRONT BUMPER GRILLE <i>X</i>	315.00
12	1	FRONT BUMPER CENTER BRACKET <i>X</i>	85.00
13	1	FRONT BUMPER FOG LAMP R <i>?</i>	235.00
14	1	FRONT BUMPER FOG LAMP BRACKET R <i>?</i>	88.00
15	1	FRONT BUMPER FOG LAMP COVER R <i>?</i>	185.00
16	1	FRONT BUMPER LOWER COVER <i>?</i>	285.00
17	1	FRONT HEADLAMP ASSY RH <i>cm</i>	955.40
18	1	FRONT FENDER RH <i>bt</i>	552.00
19	1	RADIATOR SUPPORT PANEL <i>Repair</i>	655.00
20	1	RADIATOR BRACE PANEL <i>X</i>	85.00
21	1	RADIATOR ASSY <i>?</i>	1,255.00
22	1	RADIATOR HOSE RH <i>?</i>	121.00
23	1	RADIATOR SHROUD <i>?</i>	115.00
24	1	RADIATOR FAN BLADE <i>X</i>	115.00
25	1	RADIATOR FAN MOTOR <i>X</i>	452.00
26	1	AIR CON SUCTION HOSE <i>?</i>	325.00
27	1	AIR CON CONDENSER ASSY <i>?</i>	1,150.00
			\$ 9,634.40
LESS 25%			\$ 2,408.60
			\$ 7,225.80

No	Qty	DESCRIPTION	SPEACIL NETT	AMOUNT S\$
1	6	FRONT BUMPER CLIP <i>rec</i>	6.00	36.00
2	6	RADIATOR GRILLE CLIP <i>rec</i>	6.00	36.00
3	1	HEADLAMP HOLDER CLIP RH <i>rec</i>		35.00
4	8	FRONT BUMPER LOWER COVER CLIP <i>rec</i>	6.00	30 48.00
5	1	FRONT NUMBER PLATE W/CASE <i>bt</i>		35 60.00
6	1	RADIATOR COOLANT <i>rec</i>		45.00
				\$ 260.00

**LABOUR & MISCELLANEOUS:**

1	To remove damaged parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refix and align into position refix all necessary components/attachments	800	1,200.00
---	---	-----	----------

Add Fee: ☐ Site Insp (\$

Transportation: ☐

- 2 To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials
- 3 To remove, replace radiator with all necessary components/attachments
- 4 To remove, replace air con condenser with all necessary components/attachments and recharge freon
- 5 To conduct headlamp alignment

950  
~~850 750~~ 1,200.00

100 150.00

120 200.00

30.00  
 \$ 2,780.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pass

Hp 90010068

8 days

HS

25/11/2020 @ 1640

Resy after repair

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT:

Date Of Report	24/11/2020 13:07
Date Of Accident	23/11/2020 19:30
Exact Location Of Accident	ALONG BISHAN ST 24 BLK 268A MULTI CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE:

Vehicle Registration Number	SLX8475S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THINK ONE AUTOCARE PTE LTD
Co Reg No	2XXXXX501G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96386668
Alternative Phone No	OFFICE-65453300

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 X (A)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	20-MT001761-R02
Cover Note Number	

### Driver

Name of Driver	TAY SEOW ANN
NRIC No	SXXXX533G
Date Of Birth	06/06/1968
Occupation	INDOOR
Date Of Driving Pass	28/06/1988
Driving Experience	32 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96386668
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address

BLK 267 BISHAN ST 24  
#08-166

Postcode

570267

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

-  
-  
-  
-  
-

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident

COLLISION - HEAD ON COLLISION

Weather Conditions

RAINING

Road Surface

WET

### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)  
involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by  
ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s)  
soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

ON 23.11.2020 AT ABOUT 19:30HRS I WAS DRIVING MY VEHICLE BEARING NUMBER SLX8475S SLOWLY INTO BISHAN STREET 24 BLK 268A MULTI CARPARK AFTER I CHECK THE BLIND SPOT ON MY LEFT. I DRIVE CAUTIOUSLY TOWARDS IT WAS RAINING DARK NARROW LANE. I NOTICE THAT VEHICLE BEARING NUMBER SGZ8527A WAS PARKED AND SUDDENLY MOVE AND COLLIDED INTO MY FRONT PORTION. POLICE ATTEND THE SCENE AND NO BODY WAS INJURED

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number SGZ8527A

Vehicle Make/Model/Colour TOYOTA

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver M.UNNA

NRIC/Passport Number SXXXX787Z

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

SKETCH

A - SLX8475S  
B - SGZ8527A

A

B

←

↓

↑

Bishan, S14 24  
Blk 268A  
Multi Carpark

Bishan S424  
BK 268A  
Multi Carpark

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is a vertical margin line on the left side, creating a narrow left margin. The paper appears slightly aged or off-white.

I/We declare that the foregoing particulars are true in every respect.



Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Think One Autocare Pte Ltd  
60 Jalan Lam Huat  
#02-32 Carros Centre  
Singapore 737869  
Tel: 6844 3300 Fax: 6842 4988

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	501G
Vehicle No.:	SLX8475S
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2020
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	2ZR0A61440
Chassis No.:	JTDGG20W00J008958
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	13 Apr 2018
First Registration Date:	13 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2028
PARF Rebate Amount:	\$14,966.00
COE Expiry Date:	12 Apr 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$44,000.00
COE Rebate Amount:	\$31,484.00
Total Rebate Amount:	\$46,450.00

The information contained herein is correct as at 26 Nov 2020

OK

White

x



Merimen e-Claims

x



Used 2018 Toyota Wish 1.8A for

x



PARF/COE Rebate

sgcarmart.com/used\_cars/info.php?ID=936305&amp;DL=2029

## ▶ Toyota Wish 1.8A

Overview

Financial

Accessories

Similar


Research

Photos

Map



PRIME MOTOR &amp; LEASING



CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES  
 PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Price	\$79,900		
Depreciation <sup>?</sup>	\$9,530 /yr View models with similar depre	Reg Date	27-Mar-2018 (7yrs 4mths COE left)
Mileage	N.A.	Manufactured <sup>?</sup>	2017
Road Tax <sup>?</sup>	\$976 /yr	Transmission	Auto
Dereg Value <sup>?</sup>	\$48,182 as of today (change)	OMV <sup>?</sup>	\$19,955
COE <sup>?</sup>	\$45,289	ARF <sup>?</sup>	\$19,955
Engine Cap	1,798 cc	Power	105.0 kW (140 bhp)
Curb Weight <sup>?</sup>	1,355 kg	No. of Owners <sup>?</sup>	1
Type of Vehicle	MPV		

## Features

Airbags, ABS, Reliable 1.8L DOHC Dual VVTi Valvematic Engine, CVT Gearbox, Keyless Start/Stop, Auto Climate  
 Aircon Control View specs of the Toyota Wish (2009-2018)

