

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Troger to the result of the re					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI20012987/R1sf3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	23/12/2020	
			Co	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGZ 8527A	Veh. Inspected		SLX 8475S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008096/KY	Excess (\$)		0.00	
	Assign From	ABIGAIL CHOO	Assign Date		25/11/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH 1.8 CVT	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JTDGG20W00J008958	Colour		WHITE	
	Odometer	55266 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	YOKOHAMA		5 mm	
	L/H Front Tyre	195/65 R15	YOKOHAMA		5 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA		5 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE D	DAMAGES SEE DETAILS.				
5. General Information						
	Accident Date	23/11/2020	Inspection Date		25/11/2020	
	Survey held at 60 Jalan Lam Huat #02-32 Carros Centre S737869					
	Repairer	THINK ONE AUTOCARE PTE LTD				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

8 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: