





## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/01/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SG5597A
Case Reference Number	BUS/11/20/5022
Registration Date	9/2/2017
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	Ramanathan Pannir Selvam
Type of Accident	Side Swipe
Accident Date and Time	19/11/2020 10:03 AM
Accident Reported Date and Time	20/11/2020 2:08 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108899
Special Instruction to ARC,if any	SG5597A-RIGHT REAR PORTION SHD1564F (TP) INSURED WITH NTUC
Prepared Date and Time	23/11/2020 9:22 AM
Chassis Number	YV3S4P928HA180913
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$530.00
Total Spray Cost	\$602.00	\$432.00
Total Spare Part Cost	\$765.63	\$765.63
Total Other Cost	\$0.00	(\$192.40)
<b>TOTAL COST</b>	<b>\$2,427.63</b>	<b>\$1,535.23</b>
<b>Lump Sum Total</b>	<b>\$2,450.00</b>	<b>\$1,550.00</b>
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	23/11/2020 4:29 PM	23/11/2020 5:07 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/01/2021

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	\$530.00
<b>Total Labour</b>	<b>\$1,060.00</b>	<b>\$530.00</b>

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$602.00	\$432.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$602.00</b>	<b>\$432.00</b>

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$192.40)
<b>Total Other Costs</b>	<b>\$0.00</b>	<b>(\$192.40)</b>

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			PANEL ASSY:FUEL FILL,O/S,FOR VOLVO B9TL	1.00	\$534.38	10.00	\$480.94	Replace	Replace
6012101	Body	A12-01971	O/S SIDE SHEETMETAL PANEL ( 1 )	1.00	\$529.00	10.00	\$476.10	Replace	Replace
<b>Total</b>					<b>\$1,063.38</b>		<b>\$957.04</b>		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									