

KUM CHEW MOTOR WORKSHOP

10, SIN MING DRIVE #05-08
SIN MING AUTOCITY, SINGAPORE 575722.
Tel No. : 64536256/64563715 Fax No. : 64557754
E-Mail : kumchew1@singnet.com.sg
GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3, ANSON ROAD #16-00
SPRINGLEAF TOWER, SINGAPORE 079909.
claimsdept@sg.cntaiping.com
Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES005105

Date : 26/11/2020
Vehicle Num. : SLR 4062 H
Make/Model : NISSAN SYLPHY
Chassis/Eng# :
Accident Date : 27/10/2020
Claim No. :
Reference : KC/TP4062/2011-06
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|-------|----------------------|--|--|
| 1. | 1 PC | NETT ITEMS : | | |
| 2. | 2 PCS | REAR BUMPER | | |
| 3. | 1 PC | REAR BUMPER RETAINER | | |
| | | REAR BUMPER SPONGE | | |

Nett Total S\$:
10.00% Discount S\$:

o/s m 55.10
Ben 607.00
110.20
96.80
814.00
81.40
732.60

- | | | | | |
|----|-------|----------------------|--|--|
| 1. | 1 SET | SPECIAL NETT ITEMS : | | |
| | | REVERSE SENSOR | | |

Special Nett Total S\$:

LABOUR :

- TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.
- TO SPRAY & PAINT ON REAR ACCIDENT PORTION.
- TO ANTI-RUST REAR AFFECTED AREAS.
- TO DISMANTLE & REPLACE 1 SET REVERSE SENSOR.
- TO CHECK REAR ELECTRICAL WIRING SYSTEM.

Labour Total S\$:

Shay 200.00
200.00
380.00
480.00
50.00
60.00
40.00
1,010.00

SingDollars : Two Thousand Twenty-Two & Cents Sixty Only

Not Noted Total S\$: 2,022.60

KUM CHEW MOTOR WORKSHOP

LKK Auto Consultants hence notify
the Repairer of the following:
To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Noted
L1 Pay 81000h
Benney After Paint
2 days