



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM20013043/Kps3q2 Date: 14/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 8303S	Veh. Inspected	SMR 6596J	
Policy No.	P2260282	Coverage (\$)	0.00	
Claim No.	S0M02UTN	Excess (\$)	0.00	
Assign From		Assign Date	26/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 180 COMP (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WDD2040452A728894	Colour	METALLIC PEARL WHITE	
Odometer	207058 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/50 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	01/10/2020	Inspection Date	26/11/2020	
Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			