

CS3/CTI20002103/Qsd3-1

ASS. REC. BY: <u>Surveyor: Sun Pin</u>		REF: <u>CS3/CTI20002103/Qsd3-1</u>		Special Instructions:	
ALBERT CHUA		ASSIGNMENT (Office)		25/11/2020	
From (Person): <u>Ben Tang</u>		of <u>CTI</u>		Date/Time: <u>25/11/2020 5:58pm</u>	
Estimated Cost:		Bill to:			
OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS					
To Inspect Vehicle No:		<u>SMK 2743P</u>		Insured: <u>SKU 5321A</u>	
at Workshop n/s:		<u>D's Graffiti Concepts</u>		Tel: <u>8608 3456</u>	
of <u>10 Amk Ind. Park 2A # 03-13</u>					
Policy No:		Claim No: <u>SNM20D200521 / SKU 5321A / BEN</u>			
Sum Insured:		Excess:			
Make of Veh:		D.O.A. <u>27/10/2020</u>			
(Client's Record)					
CA / REV / REP. / REV 24 HRS <u>lup</u>		H.O.B. Endorsement:			
Date/Time: <u>9:34am 6/2/2020</u>		Person Contacted: <u>Dave</u>		Vehicle <u>IN / OUT</u>	
Date/Time	Action/Instruction	Initials (X)			
	<u>SMK 2743P - X</u>				
	<u>SKU 5321A - X</u>				
	SUBMIT L/S \$8,400.00/9 DAYS				
	(\$ 13,300.00/RED - 61%)				

ASS. REC. BY: Sun Pin.

REF:

CT3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMK 2743 P.

Yr Regn: 15/04/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Axio

c.c 1496

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NET260-3042958

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185 / 70 R14

R: 185 / 70 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

5 mm

L/Bal.

5 mm

D.O.A.

27/01/2020

D.O.I.

06/02/2020

Survey held at

Des. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10 GIA 86083456 Mr Dan	
MV: 20,000	
PR: 10,413	
NV: 9,081	
	Repair dy - 8 days
	Repair Kung - 8k-9k
	18/2/2020

Date/Time, File Pass to?

20/02/20

1) Type

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I. /

☐ : Prel. Report☒ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Wash and (\$

Survey Fee:

Transportation:

S + RS, SI

Police

Others

TOTAL

190