

CS3/CTI20002103/Qsd3-1

ASS. REC. BY: Sun Pin REF: CS3/CTI20002103/Qsd3-1 Special Instructions:
Surveyor: ALBERT CHUA ASSIGNMENT (Office) 25/11/2020
From (Person): Ben Tang of CTI Date/Time: 25/11/2020 5:58pm
Estimated Cost: _____ Bill to: _____
OD # TP / WS / TP RES / OD RES / EVA / INV / MV / CS
To Inspect Vehicle No: SMK 2743P Insured: SKU 5321A
at Workshop n/s: D's Graffiti Concepts Tel: 8608 3456
of 10 AMK Ind. Park 2A # 03-13
Policy No: _____ Claim No: SNM20D200521 / SKU 5321A / BEN
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 27/10/2020
(Client's Record)
CA / REV / REP. / REV 24 HRS lup H.O.B. Endorsement: _____
Date/Time: 9:34am 6/2/2020 Person Contacted: Dave Vehicle: IN / OUT

Date/Time	Action/Instruction Initials (X)
	<u>SMK 2743P - X</u>
	<u>SKU 5321A - X</u>

ASS. REC. BY: Sun Pin.

REF:

CT3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMK 2743 P.

Yr Regn: 15/04/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Axio

c.c 1496

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NET260-3042958

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185 / 70 R14

R: 185 / 70 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

5 mm

L/Bal.

5 mm

D.O.A.

27/01/2020

D.O.I.

06/02/2020

Survey held at

Des. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA 86083456 Mr Dan

MR 20,000

PR: 10,413

NR: 9,081

Repair dy - 8 days

Repair Kung - 8k-9k

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I. /



: Prel. Report



: Final Report

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Wash and (\$

Survey Fee:

Transportation:

S + RS, SI

Phone

Others

TOTAL

190

190