

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC3/CT1200/3076/4e23

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHA 44951

at Workshop m/s

Comfort Del

of

SKU 1199M

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rport:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHA 44951

Yr Regn:

819

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

SA /

Make:

Hyundai AEIONIQ

C.C

1580

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp.Reading

119906

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHC85 / CVKU165194

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R 15-

R:

Wetlake

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

5

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

25/11/20

D.O.I.

26/11/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

LKc

CHINA

COMFORTDELGRO ENGINEERING PTE LTD

Date: 25.11.2020

Time: 14:39:10

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305435479
REGN NO : SHA4495D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 06.08.2019
DATE/TIME IN : 25.11.2020 11:15
ACCIDENT DATE : 25.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	DL ✓
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	DL ✓
0003 04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1 L	451.25	20.00	361.00	DL ✓
0004 04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1 L	155.00	2.00-	155.00	2 X
0005 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	0.20	180.00	?
0006 04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	0.02-	50.00	DL ✓
0007 FNPS	NO PLATE(S) WITH TRIM COV	1 N	55.00	0.00	55.00	DL ✓

SUB-TOTAL : 1,186.12

JOB NATURE

0000 L	PANEL BEATING	350.00	- 320
0001 23-502	SPRAYPAINT ON AFFECTED AREA	250.00	- 200
0002 20-22	REMOVE/REFIX REVERSE SENSOR	80.00	- 40

SUB-TOTAL : 680.00

not Authorized

HP 90096608

26/11/20

P/P

2 days before recovery.

Email - marcus@lkc-auto.com

member of COMFORTDELGRO

Date/Time: 25.11.2020 13:55 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.:305435479

FROMER
AS COMFORT TRANSPORTATION PTE LTD
FROMER NO. 7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)
OUNT CARD NO.


REGN NO. SHA4495D	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 25.11.2020 11:15
YR OF MANU. 06.08.2019	TARGET DATE
CHASSIS CODE KMH851CVKU165194	COMPLETION DATE/TIME:

CHINA

JOB DESCRIPTION

Accident Date: 25.11.2020
NATURE: 3P 25.11.2020

3/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

No.: SHA4495D

LKE

Steve

Exit Pass

Vehicle No.:

SHA4495D

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305435479
REGN NO : SHA4495D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 06.08.2019
DATE/TIME IN : 25.11.2020 11:1
ACCIDENT DATE : 25.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,866.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/11/2020 13:16
Date Of Accident	25/11/2020 09:45
Exact Location Of Accident	BT TIMAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4495D
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	SAMRI BIN HASSAN
NRIC No	SXXXX409Z
Date Of Birth	10/03/1962
Occupation	OUTDOOR
Date Of Driving Pass	14/11/1996
Driving Experience	24 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90995090
Fax Number	
Contact Number	
Email Address	SAMRIHASSAN01@GMAIL.COM

Address	438 #06-408 FAJAR ROAD
Postcode	670438
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : -
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKU1199M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT & REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMM3368Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage FRT

No. Of Passenger (Including Driver)


SKETCH PLAN

A - SHA 4495D

B- SKU 1199M

C-SMM 3368 Y

12T TIMAH RD



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

no statement attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)

Date & Time: 25.11.2020
1130h

Reporting Centre Personnel's Signature
Name: **Larry Ng**
NRIC/Fin No.:

Sketch Plan Pg. 2

Describe Circumstances of the Accident.

On 25.11.2020, at about 0945hrs, I was driving my Comfort taxi, SHA4495D, on the right lane along Bt Timah Rd with 1 male pax.

Weather was clear and moderate traffic. Somewhere after the Hume Ave, the front vehicles braked and stopped. I stopped too.

Right after I had stopped, I felt an impact from the rear. I went out to check and saw a private car, B, had hit my taxi rear. There was another car, C, that had hit B rear involved in the chain collision. I have a video recording of the accident impact. Photos taken at the scene.

No injury at the time of accident.

Declaration

I/We declare the foregoing particulars are true in every respect.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature/Date &
Time

Driver's Signature (If driver is not the policyholder)/Date
& Time

Larry Ng
Witnessed by Reporting
Centre Personnel

25.11.2020
1130w



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA4495D
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Nov 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU299930
Chassis No.:	KMHC851CVKU165194
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,018.00
Original Registration Date:	06 Aug 2019
First Registration Date:	06 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$12,026.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Aug 2027
PARF Rebate Amount:	\$9,019.00
Intended COE Rebate Details	
COE Expiry Date:	05 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,463.00
COE Rebate Amount:	\$19,631.00
Total Rebate Amount:	\$28,650.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Nov 2020

OK