

ASS. REC. BY:

REF:

CS/AIG20013079/Eqd3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

1800049096

Claims No.

4573514486SG

Sum Insured:

Excess:


600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Turn Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLZ S267K

Yr Regn:

8/5/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c. 1591

Colour:

1998 Grey

A/C: Insured / Std / NI / N

Sp. Reading

19286

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNAFX 411 MJS 765707

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

\$

mm

R/Bal.

\$

mm

L/Bal.

\$

mm

L/Bal.

\$

mm

D.O.A.

29/10/20

D.O.A.

26/11/20

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-63K

27/11/20@11.38am revert to AIG via Merimen.

30/11/20@9.39am Lois Chang informed C/A via Merimen.

30/11/20@10.38am Informed Don Bong C/A & ex:\$600 by email

10/12/20@12.33pm confirmed with Larry final fig \$4737.60, 5 days (Red \$1356.40, 22%)

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Rep. Form:

MER-OD

Comp. No. / L.E. / C.

4737.60



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Ng Hai Kiat Reg No/Reg Date SLZ5267K# / 08/05/201 Date In/Mileage / 0 Chassis No KNAFX411MJ5765707 Engine No G4FGJH695883 Make/Model KIA/CERATO K3 1.6 A EX CAP Colour/Trim DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	26/11/2020/ 16:01	QUD	247 / DonBong	23572
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON RH FRONT DOOR PANEL 480 RH REAR DOOR PANEL					800 1200.00
E PNT88000 REMOVE AND TRANSFER RH FRONT DOOR GLASS, TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL					120.00
E PNT98000 PAINT WORK SPRAY RH FRONT DOOR PANEL, RH REAR DOOR PANEL 350 AND AFFECTED PORTION * RH Sill panel - cut					1050.00
M SUNDRY APPLY BODY SEALANT					80 120.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM					30.00
M SUNDRY PERFORM RUST PREVENTION					40 120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00
E PNT88000 REMOVE AND TRANSFER RH REAR DOOR GLASS, TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL					120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment					120.00
M SUNDRY SUNDRIES					20 50.00
M PANEL ASSY-FRONT DOOR, RH		1.00	1542.00	20.00	1233.60
M COVER-FR DR O/S HDL, DRIVER		1.00	22.00	20.00	17.60
M HANDLE ASSY-DOOR OUTSIDE		1.00	58.00	20.00	46.40
M BASE ASSY-FR DR O/S HANDLE RH		1.00	52.00	20.00	41.60
M LATCH ASSY-FRONT DOOR, RH		1.00	253.00	20.00	202.40
M CHECKER ASSY-FRONT DOOR, RH		1.00	32.00	20.00	25.60
M BLACK TAPE-FR DR FRAME UPR, RH		1.00	13.00	20.00	10.40
M BLACK TAPE-FR DR RR, RH		1.00	12.00	20.00	9.60

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name	/Ng Hai Kiat
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date	SLZ5267K# / 08/05/201
78 SHENTON WAY #08-16	Date In/Mileage	/ 0
AIG BUILDING	Chassis No	KNAFX411MJ5765707
SINGAPORE 079120	Engine No	G4FGJH695883
Contact No 64191000	Make/Model	KIA/CERATO K3 1.6 A EX CAP
	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	26/11/2020/ 16:01	QUD	247 / DonBong	23572			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL ASSY-REAR DOOR,RH ✓				1.00	1361.00	20.00	1088.80
M	COVER-FR DR O/S HDL,PASSENGER X				1.00	22.00	20.00	17.60
M	HANDLE ASSY-DOOR OUTSIDE X				1.00	58.00	20.00	46.40
M	BASE ASSY-FR DR O/S HANDLE RH X				1.00	52.00	20.00	41.60
M	LATCH ASSY-REAR DOOR,RH X				1.00	309.00	20.00	247.20
M	BLACK TAPE-RR DR FRAME UPR,RH ✓				1.00	11.00	20.00	8.80
M	TAPE-RR DR FRAME BLACK RR,RH ✓				1.00	8.00	20.00	6.40

Estimate

SURVEYOR NAME: Steve CLKK 26/11/20, 4.30pm

SURVEYOR SIGNATURE: _____

DATE: _____

REMARKS: _____

DD- Not Auth
EXCISE - ?
5 days
P/P
My Bel say

Confirm & accepted by

7% GST on	Nett	6,094.00
	6094.00	426.58
Total Payable		6,520.58

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.