

ASSIGNMENT

From: Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SHA 62063*

at Workshop m/s

of

Insured:

Policy No.

MR005701

Claims No.

M2005861

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

13.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

019B

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHA 62063

Yr Regn:

4.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Hyundai AC IONIQ

c.c

1580

Colour

blue

A/C:

Insured / Std / NI / NA

Sp. Reading

211278

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHC851CVKU146253

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxlake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/11/20

D.O.I.

27/11/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*30/11/20 Confirmed final fig \$1451.16 with MR Lim (Red \$1084.68, 43%)**30/11/20 @ 9.14am revised to Francis Ng via Messenger.*

Date/Time, File Pass to?

☐

: Preli. Report

1) *30/11/20*☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

MR-TP

Lump Sum / I.B.I. (\$

1451.16

ComfortDelGro Engineering Pte Ltd (Co. Reg No. 199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

Lim Tien Siong

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)

CTPL

Singapore

marcus

CLKK-Steve

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	26/11/2020
Vehicle Reg. No.:	SHA6206J	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	30/04/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU211003	Chassis No:	KMHC851CVKU146253
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	32		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

not Action
done
P/P 1451-16
MP90096608
marcus@lkkauto.com

COST OF CLAIMS

Amount

Parts	1,804.84
Miscellaneous Items	11.00
Labour	720.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$)	2,535.84
+ GST 7.00% (\$\$)	177.51
Nett Amount (\$\$)	2,713.35

This claim is handled by: LIM TIEN SIONG

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Nov 2020)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA6206J/26/11/2020 15:30**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BUMPER <i>De/harped</i>	20.00	0.00	*459.40 FL	✓
2	1		*REAR BUMPER CENTER MOULDING <i>one</i>	20.00	0.00	*451.25 FL	✓
3	1		*REAR BUMPER LOWER MOULDING <i>1</i>	20.00	0.00	*155.00 FL	X
4	1		*REAR BUMPER REINFORCEMENT <i>1</i>	20.00	0.00	*394.80 FL	X
5	1		*REAR BUMPER REINFORCEMENT STAY LH <i>1</i>	20.00	0.00	*138.10 FL	X
6	1		*REAR BUMPER FOGLAMP <i>1</i>	20.00	0.00	*201.50 FL	X
7	1		*REAR BUMPER REFLECTOR LH <i>1</i>	20.00	0.00	*41.45 FL	X
8	1		*REAR BUMPER TOW COVER <i>1</i>	20.00	0.00	*98.80 FL	✓
9	10		*REAR BUMPER CLIPS <i>1</i>	20.00	0.00	*22.00 FL	✓
10	1		*REVERSE SENSOR <i>1</i>	0.00	0.00	*180.00 F	X
11	1		*REAR NO.PLATE WITH TRIM COVER <i>one</i>	0.00	0.00	*55.00 F	✓

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **2,197.30**- List Item Discount on L Items (S\$) **392.46**Total Parts (S\$) **1,804.84**

ComfortDelGro Engineering Pte Ltd/SHA6206J/26/11/2020 15:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1031.45
20%
825.16
1457.16

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	350.00
2	SPRAY PAINTING	New	250.00
3	R/I REVERSE SENSOR	New	120.00
Gross Labour Cost (S\$)			720.00

ComfortDelGro Engineering Pte Ltd/SHA6206J/26/11/2020 15:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Workshops

59 Loyang Drive Singapore 508989
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Pandan Road Singapore 609649

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 729791
501 Yishun Industrial Park A Singapore 768732

member of COMFORTDELGRO

Date/Time: 26.11.2020 15:19

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.:305435852


OWNER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO. SHA6206J	MILEAGE
	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G2)	DATE/TIME IN 26.11.2020 13:20
	YR OF MANU. 30.04.2019	TARGET DATE
	CHASSIS CODE KMHC851CVKU146253	COMPLETION DATE/TIME:

OUNT CARD NO.

JOB DESCRIPTION

Accident Date: 26.11.2020
NATURE: 3P 26.11.2020

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Checklist/Signature Slip

Exit Pass

Vehicle No.: SHA6206J

LIMITS

Vehicle No.:

SHA6206J

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard