ASS. REC. BY: Ster 1 HEF: CS/AIG	70013140/Esf3
ASSIGNMENT	
From: Dale:	Veh No: SMH S763C Yr Regn: 28/1/19
Estimated Cost:	Type M.Car / M.Cycle / Bus / Van / Lorry /.Taxl / Prime Mover /
( OD) IP I WS/ IP RES / OD RES / EVA / INV / MY	Truck / Traller or
To Inspect Vehicle No:	Make: Milsvishi Attrace c.c 1193
et Workshop m/s	Colour Site (ILA . AVC: Insured / Std / NI / N
ol .	Sp.Reading X70914 T/Radio: Insured / Std / NI / N
Insured:	Eng/No:
	" 1007110001
Policy No.	CNO: MM SSTATSAKH U91941
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: \$600.00	Sleering: Inforder / Jammed / Leaked / Burnt or
(Clioni's Record)	Brake: Inforder / Jammed / Leaked / Burnt or
Make of Veh;	Modi: Nii / S/Righ / STD A/Rim gr
table 1.4 Million on the control of Million Control	Tyre Size: F: 195/55 R15
(Policy Condition)	R: (1
Remark: The veh had commenced its NS '' 'O/S	BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
repair at the time of inspection.	TOYO / YOKO or
L ALA	1010110KO 61 -
Bal. or Market Value:	Fron! Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal, 4 mm R/Bal. 4 m
SIA / PR Seen: Consistent? : Yes or No	L/Bal. 4 mm UBal. 4 m
Est. Repairs; days Res.: Yes or No	D.O.A. 99/11/29 D.O.I. 79/11/29
2 Vol. Von et No.	Survey held at (ycle & Carling
Lum Sum: % 3 Val.: Yes or No	Sulvey held at
CA   REV   REP.   24 HRS	Des. of Damages : Frt (Rea) / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	W. L. L. L. Collision
Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
Mr-54K	<u> </u>
<u>'</u>	
P/P \$3,595.89/4 DAYS, FINALIZED WIT	H ANDRE
(\$1,681.11/RED - 32%)	
1, 17611, Noper	ys Of Repair: 4
21/12/2020 Res	survey No. of Trip: 1 Survey Fee:
	Transportation:
Add Fee:	: Site insp (\$ )s + RS,Si
op of orms:	: Tech. mvs
Hittp State LE.I: 7 P/P \$3,595.89	: Weel and (8
	. rotal