ASS. REC. BY: RASIL REF: CS/AMA 2	4001314/R1 f3 1 446w
AS	SIGNMENT
From: Date:	Veh No: SLW 6398A Yr Regn: 2018 IFEB
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry /. Taxl / Prime Mover /
OP TEN WEST PRESION RESIEVALINVINV	Truck / Trailer or
To Inspect Vehicle No: SLW 6398A	Make: Volksmacken passay 20 RLc.c 1984
at Workshop m/s Confort Muhlo	Colour Brown A/C: Insured / Std / NI / NA
of 45, Parson Rs	Sp.Reading 2-8784 T/Radlo: Insured / Std / NI / NA
nsured: KWØ	Eng/No:
Policy No.	CNO: WVW2223CZHE 201421.
Claims No.	Gen. Cond: Good (Falr) Poor / Burnt
Sum Insured: Excess: 550	Steering: Inorden/Jammed/Leaked/Burnt or
(Client's Record)	Brake: (norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 235 40R19
(Policy Condition)	R:
	BS DUN EXNOVA GY FS LIZA MIC OHTSU FR SUMI
repair at the time of inspection.	TOYO / YOKO or .
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? ; Yes or No	R/Bal, R/Bal. 6 mm
	UBal, rnm UBal. 6 . mm
	0.0A. 21/1/2000 0.0.1. 01/2/2020
0 1/4 1 V 1/2	Survey held at Comfort
	Des. of Damages, Frt Rear O/S N/S U/C Rooftop or
CA I REV I REP. I 24 HRS	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
	· · · · · · · · · · · · · · · · · · ·
- - xi 	
- Providency	
DaleMine, File Pass to? Preit. Report	Days Of Repair:
Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	· Transportation:
. 2) Ac	dd Fee: :Site Insp (\$)s+RSSI
	: Interview (\$) Photos
Rept Formal:	: Tech, Invs (\$) otion
Lump Sun / L.B.H. (%)	: Weel and (%
	Legitime.
	YOTAL
· · · · · · · · · · · · · · · · · · ·	. 7

COMFORTDELGRO ENGINEERING 45 Pandan Road S (609286)

ACCIDENT REPAIR ESTIMATES

Our Ref:						
Type of Claim : X Own Dama	ige	Vehicle No.	:	SLW6398A		
3rd Party		Make & Model	i	VOLKSWAGEN / TSI HUD		
Windscreen	n	Year of Manufacture	:	2017		
		Chassis No.		WVWZZZ3CZHE201421		
Ins Company : AV	VAC	Engine No.	:	CHH209768		
Excess :T	ВА	Policy No.		BVFPSB0006822008		
Date of Accident : 21.1	1.2020	Time of Accident	:	10.45 A.M		
Suggested Days of Repair :	6 DAY	In-house Vehicle Asse	essc	or.		
Repair Estimates		Name	:	Wong Chee Wei		
B. 1. () . Q. (() . ()		Signature				
Parts (a) Cost / List Price Items	\$5,262.00	Contact No		68676919		
Plus/Less 10 % _	\$526.20			HP: 97239882		
(b) Nett Price Items						
Less%						
(a) Special Nett Items	\$205.00					
(c) Special Nett Items	\$205.00					
Total Parts Cost (Appendix A)	\$5,993.20					
Labour (Appendix B)	\$2,060.00					
Total Repair Cost	\$8,053.20					
The above total will be subjected to 79	% G.S.1.					
Name of Surveyor	: Rasu	-LKK				
Company	: LKK					
Survey conducted on	: 01/12/20	370 at	41	O		
Remarks By Surveyor	ſ,					
(a) The repair of this vehicle is auth	norized / is not authori	zed until further notice				
(b) Recommended Days of Repair	. 1	day(s) P/P				
(c) Resurvey	· (Paguired Mat 5	Description 1				
(d) Excess :\$_ \int \formall Resurged Resu						
(e) Signature of surveyor	: <u>f</u>	Date:	-	01/12/2020		
WCCIDENT REPAIR ESTIMATESIF3						

COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609286) Tel: 68676919 Fax: 62626950 Appendix A

e Parts	SL	W6398A	Submit By		Wong Chee Wei
9 140.		PASSAT VARIANT R-LINE TSI HUD			2017
& Model: . is No. : .	WVWZ	ZZ3CZHE201421	Engine No.	: _	CHH209768
					OD

-			
	m	rd	
		ıu	

S/No	Part Description	Qty		Price	Nett	List	S- Nett	Diposition By
			original	OEM	Price	Price	Price	Surveyor
1	FRONT BUMPER De/	1	\$650.00					1
2	FR BUMPER CLIP No /	10	\$30.00					
3	FR BUMPER SIDE RETAINER,LH	1	\$26.00			V		
4	FR BUMPER SIDE RETAINER,RH 💢	1	\$26.00					
	FR BUMPER UPPER BRACKET,LH ?	_ 1	\$30.00					
6	FR BUMPER UPPER BRACKET ,RH ?	1	\$30.00					
7	FR BUMPER SPONGE ?	1	\$80.00					
8	FR BUMPER REINFORCEMENT 7	1	\$250.00					
9	FRONT GRILLE CHROME CA	1	\$680.00					
	LOGO-FR CM/	1	\$65.00					
11	LEFT HEADLAMP ?	1	\$950.00					
	LEFT HEADLAMP CHROME MOULGING ?	1	\$40.00					
13	RIGHT HEADLAMP ?	1	\$950.00					
	RIGHT HEADLAMP CHROME MOULDING 7.	1	\$40.00					
15	FRONT SUPPORT PANEL ?	1	\$450.00					
16	BONNET 51-	1	\$750.00					
17	BONNET INSULATOR CLIP MAY	15	\$45.00					
18	BONNET LOCK X	1	\$120.00					
19	BONNET FR SEAL,RH 🎎 /	1	\$25.00					
	BONNET FR SEAL ,LH / /	1	\$25.00					
	FRONT NO.PLATE de/	1					\$45.00	
22	RADIATOR COOLANT ?	1					\$60.00	
	AIR CON GAS & OIL ?	1					\$100.00	
24		1						
25		1		7				
26		1						
27		1						
28		1						
29		1						
30		1						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

COMFORTDELGRO ENGINEERING PTE LTD

Appendix B

45 Pandan Road S (609386) Tel: 68676919 Fax: 62626950,68676903

		_		-
-	n	0	11	
~	v	v	•	

Vehicle No.	: _	SLW6398A	Submit By	:	:	Wong Chee Wei	
Make & Model	: _	VOLKSWAGEN	Year of Manufactur	e :	8	2017	

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO REMOVE,REPLACE,RE ALIGN : FR BUMPER,BONNET,SUPPORT PANEL AND ACCIDENT AFFECTED AREA	\$1,200.00	400
2	TO PUTTY,RE SPRAY PAINT :FR BUMPER,BONNET,	\$800.00	fou
3	TO CHECK WIRE AND FOCUS HEADLAMP	\$60.00	30
	LKK Auto Consultants hence notify		
	the Repairer of the following:		
	To resurvey before/aller spray painting To display damaged part(s) during resurvey To display damaged part(s) during resurvey		
	 Parts prices are subject to confirmation 		
	Third party survey is on a Without Prejudice" basis No illegal modification(s) is allowed		
	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
			
1	Acknowledged by Repairer		
-	Signature: Date:		
		-	
		†	
_			
1			
-			
-			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

103537 / STA INSPECTION PTE LTD - Boon Lay NOTE & TIME: 23/11/2020 08:10 V DATE & TIME: PROPERTY OF THE P

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 2. This remains provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT: STATEMENT

Date Of Report 23/11/2020 08:10 Date Of Accident 21/11/2020 10:45

Exact Location Of Accident BUKIT TIMAH PLAZA - CAR PARK

Country/State of Loss SINGAPORE

II DETAILS OF OWN VEHICLE

Vehicle Registration Number SLW6398A

Insured/Policyholder

Name Of Registered Owner LIEBHERR-SINGAPORE PTE LTD

Co Reg No

Email Address ISKRONER@GMX.CH Mobile Phone No (LOCAL) +65-96658592 OFFICE-96658592 Alternative Phone No

Vehicle Particulars

VOLKSWAGEN Manufacturer

PASSAT Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

PRIVATE CAR Vehicle Category

Insurance Company

ALLIED WORLD ASSURANCE COMPANY, LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

BVFPSB0006822008 Policy Number

Cover Note Number

Driver

Name of Driver KRONER GEB MISSBACH INA

Passport No/FIN GXXXX179P Date Of Birth 02/10/1980 Occupation INDOOR Date Of Driving Pass 04/03/2019

Driving Experience 1 YEAR AND 8 MONTHS

Gender **FEMALE**

Mobile Number (LOCAL) +65-96658592

Fax Number

OFFICE-96658592 Contact Number ISKRONER@GMX.CH **EMail Address**

Address

78F YUK TONG AVE

Postcode

596209

r usicoue

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - SPOUSE OF EMPLOYEE

Vehicle Registration Number of Driver's Own

Vehicle

_

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

NO

ambulance?
Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

LEDETAILS OF OTHER VEHICLE PROPERTY 11

Vehicle Registration Number

SJJ5678R

Vehicle Make/Model/Colour

NA

Details Of Properties

REAR PORTION

Vehicle Category

PRIVATE CAR

Name of Driver

JINGYUNGI

NRIC/Passport Number

SXXXX700B

Contact Number

93868659

Address

NA NA


Postcode

Insurance Company Name

Nature Of Damage

reactive of Darnage

No. Of Passenger (Including Driver)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

OF THE ACCIDENT			
Placa	Car porc	21/11/2020	10:45am
guise in	and as initi	·~)	slot and n front of the
2		22	11/2020
	Placa Guisc in Guisc in Got in Front.	Placa Carporc SC, I was looking for guise in time that	Placa Car pose 21/11/2020 CC. I was looking for a empty of guise in time I that the cat is (Stop and go waiting) got in contact with the rear front.

Sketch Plan #2



IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lundersland, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form: and any other personal information provided by me or possessed by my insurer (to lectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - processing, handling and/or dealing with my claims including the settlement of the daims and any necessary investigations relating to the claims;
 - (i) investigating the accident and/or my claims;
 - (II) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, hand ing and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including the illumyers/ aw firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Pulceholder's Signature

Dele & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time

Report of Centry Personnel's Signature

Name:

NRIC/-IN No.

➤ Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ttretestra i alternacioni periodi a elegimente de comunicacione de comunic
energi produje prija kraživim prija a prija produkta prija in translati prija prija prija prija prija prija pr
eki selan banga angan bang pilikalan bangsan menanggan bernggan bangsan menang
tem de ado (1.16) de promotora o plandojno de adojaŭo deparante promotora addinaŭojnojn
agantantana dan kanana kanan kanan dan kanan
R-LINE 2.0 TSI HUD
and the control of th
201421
p)
Paraci (nastonos) especarjen aponinani (nipras) parkitarina (nipras) (nastonos)
Confestions, 1977 (Frankstrum) (Abrillato) (1978)
изэээн цинг салын том даан доссанан царцаган алыгын алыгын алыгын алыгын
9-10-130: 144-1430: 120-14-1-130-14-1-1-1
art di salis un il 1777 i il 1880 i 1777 i il 1880
ante estante estatuan (interior ante estatuan estatuan estatuan estatuan estatuan estatuan estatuan estatuan e
c or 97kW (130bhp)
COL 47KVV (130bhp)
and the second s
The standing of the property o
ar i maga la maga para maga ang panas ng panas n

ОК



mart.com/used_cars/info.php?ID=940903&DL=2430

▶ Volkswagen Passat Variant 2.0A TSI R-Line

Overview	Financial Accessories	Similar Resear	ch Photos Map
Price	\$116,300		
Depreciation ①	\$12,970 /yr View models with similar depre	Reg Date	24-Jan-2018 (7yrs 1mth 22days COE left)
Mileage	57,000 km (20k/yr)	Manufactured ①	2017
Road Tax ①	\$1,194 /yr	Transmission	- Auto
Dereg Value 🗇	\$67,706 as of today (change)	OMV ①	\$39,365
COE ①	\$45,289	ARF ()	\$47,111
Engine Cap	1,984 cc	Power	162.0 kW (217 bhp)
Curb Weight ()	1,550 kg	No. of Owners 🕚	1
Type of Vehicle	Stationwagon		

220BHP Turbocharged Engine, 350Nm Torque, 6 Speed Gearbox, 0-100km/h In 6.9 Sec, 8" Touch Screen, Bluetooth, Navigation, DVD, 2 SD Cards, 8 Speakers View specs of the Volkswagen Passat (2005-2011)

Accessories

Features

19" Alloy Rims, R-Line, Keyless System, Auto LED Headlights, LED Daytime Running Lights, ISOFIX, Panoramic Sunroof, Cruise Control, All Round Sensor.



