## **Munich Autocare Pte Ltd**

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869 Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

Not Notheries
Why &
Runny After Pains

**Vehicle No** 

: SMQ8961E

: OPEL, ASTRA ST 1.6 TURBO DIESEL Make & Model

(A),W0VBD8EG9K8031419

<b>ESTI</b>	MAT	JON	REP	ORI

Estimation No. : E20120001 : 02/12/2020

No.	Description	Q	ty	U/P		Amt	•
	Section: Remark						
1	CHINA TAIPING INSURANCE SINGAPORE PTE LTD DOA: 27.11.2020	1.	00	0.00		0.00	
		Dis	coun	Amt t (0.00%) Subtotal	9	\$ 0.00 \$ 0.00 \$ 0.00	
	Section: Parts	. 10					,
2	39113368 REAR BUMPER	clau 1.	00	1,190.40	1,	,190.40	٠
3	13426391 BRACKET CENTRE	1.	00	48.00		48.00	
4	39193222 REAR END PANEL	1.	00	648.00			
5	90766405 REFLECTOR LH	1.	00	28.80		28.80	
6	90766404 REFLECTOR RH	. 1.	00	28.80	In	28.80	)
		Disc	ount	Amt (10.00%) Subtotal	S\$		
	Section: Labour	1	.00	200.00		200.00	,
	LABOUR FOR REMOVE & TRANSFER PARTS TO NEW BUMPER		.00	400.00		400.00	
	LABOUR FOR REPLACE REAR END PANEL AND PANEL BEATING AFFECTED AREAS	•	.00	400.00		400,00	•
		Di	scou	Amt (0.00%) Subtotal		600.00 \$\$ 0.00 \$ 600.00	)
	Section: Spray paint						
	LABOUR FOR SPRAY PAINT REAR BUMPER	1	.00	400.00	)	400.0	0
	LABOUR FOR SPRAY PAINT REAR END PANEL	, ,	.00	400.00	)	400.0	0
0	LKK Auto Canality (shence notify the Rapa to the whole the Torrest of return to the transfer of the transfer o	D	iscou	Am int (0.00% Subtota	)	\$ 800.0 \$\$ 0.0 \$\$ 800.0	0
	Part of an expect to c  Thild part, services on tell basis  No illegan of the services of the						
	Ac' Sarah S.						
	Sig Date		Part	k Subtota s Subtota	I S	S\$ 0. \$ 1,749	.6
				ır Subtota nt Subtota	1	S\$ 600. S\$ 800.	0.

Total S\$ 3,149.60

PAGE 1 OF 1

## IMPORTANT NOTICE

Contact Number

**EMail Address** 

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
   This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aloresalu.	ACCIDENT STATEMENT
Date Of Report	27/11/2020 14:07
Date Of Accident	27/11/2020 12:10
Exact Location Of Accident	GRANGE ROAD
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SMQ8961E
Insured/Policyholder	
Name Of Registered Owner	BIS MOTORING PTE LTD
Co Reg No	2XXXXX055D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-86881311
Vehicle Particulars	
Manufacturer	OPEL
Model	ASTRA-H 1.6 (MTA)
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO ,
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	VFX/P2334014
Cover Note Number	
Driver	
Name of Driver	NOR'HISHAM BIN OSMAN
NRIC No	SXXXX973F
Date Of Birth	19/07/1970
Occupation	OUTDOOR
Date Of Driving Pass	16/10/1999
Driving Experience	21 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-81702731
Fax Number	

NOEMAIL

Page 1 of 13

Address

119 PENDING ROAD

#03-260

Postcode

670119

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

•

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

...

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: PASSENGER

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SME852C

Vehicle Make/Model/Colour

BENTLEY

**Details Of Properties** 

PRIVATE CAR

Vehicle Category Name of Driver

**CHEN SHUXIAN** 

NRIC/Passport Number

GXXXX790U

**Contact Number** 

88620999

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 13

- GRANGE	ROAD
8	A
SCRIBE CIRCUMSTANCES OF THE ACCIDENT	
On 27 11 2020 (a) 12:	12 pm drivi while I sto
Whon traffic turn	green in my favour,
suddenly Wehicle B	Uhit my rear portion.
	J
Negron and	
M. M	

