

REF:

SGF6696M. Yr Regn: 2016, March

Veh No: SG+6686/M. Yr Regn: 2016 / Mar 14

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Florida Vezel C.C. 1496

Colour Whole A/C: Insured / Std / NI / NA

Sp. Reading 360143. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11107262 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

	
N/S	O/S

Tyre Size: F: 215/60R16.

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. 86 mm	R/Bal. 86 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 30/11/20

*Survey held at Leary.

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP AIG.
	MV :
	PV :
	Nett:

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ _____) ☐ : S + RS. _____ \$
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.J.: 0

Survey Fee:

Transportation:

$$S + PS \rightarrow SI$$

Photos

Others

TOTAL