

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305436671
 REGN NO : SH 8326R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 11.01.2017
 DATE/TIME IN : 28.11.2020 08:20
 ACCIDENT DATE : 27.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	de
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	rec
0003 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	rec

SUB-TOTAL : 952.40

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

SUB-TOTAL : 680.00

TOTAL : 1,632.40

MVA NAME & SIGNATURE

DATE : 01/12/20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Tanphie 97495744
 'WP' 1/12/20 @ 4pm
 • 2 days
 1/5 Resurvey after repair
 Tanphie @ lkkauto.com

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408648

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 7687

Date/Time: 01.12.2020 13:34

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.:305436671

COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)
UNT CARD NO.

REGN NO.: SH 8326R	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 28.11.2020 08:20
YR OF MANU. 11.01.2017	TARGET DATE
CHASSIS CODE KMHLB41UMHU098188	COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 27.11.2020
NATURE: 3P 27.11.2020

/NO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SH 8326R

JU AIG

Vehicle No.:

SH 8326R

Service Advisor

Signature/Date

Name of Service Advisor

Date