

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	NCE BHD	Ref:	CS3/LPC20008987/R1tf3e2-1	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	14/12/2020	
			Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 6110X	Veh. Inspected	SMT 8801T	
	Policy No.	Z19VC05004351	Coverage (\$)	0.00	
	Claim No.	19/20/20/VC05/023575	Excess (\$)	0.00	
	Assign From	GERALD POH	Assign Date	01/12/2020	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E180 SEDAN AVG	c.c	1497	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	W1K2130762A764691	Colour	BLUE	
	Odometer	10064 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/55 R17	MICHELIN	6 mm	
	L/H Front Tyre	225/55 R17	MICHELIN	6 mm	
	R/H Rear Tyre	225/55 R17	MICHELIN	6 mm	
	L/H Rear Tyre	225/55 R17	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	24/08/2020	Inspection Date	26/08/2020	
	Survey held at	TG2K SPRAY PAINTING CENTRE			
		BLK 1010 BUKIT MERAH LANE 3 #01-117 SINGAPORE 159724			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	5 Work	ing Days	