



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013189/T1Kvf3n2	
			Date: 15/04/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 491P		Veh. Inspected	SMQ 3499G
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2003479/RUC		Excess (\$)	0.00
Assign From	GRACE TEO		Assign Date	01/12/2020
2. Vehicle Particulars & Condition				
Make & Model	KIA CERATO		c.c	1591
Engine No.	HIDDEN		Year of Reg.	2019
Chassis No.	KNAF3416MK5051940		Colour	DARK BLUE
Odometer	11617 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre	205/55 R16		KUMHO	6 mm
L/H Front Tyre	205/55 R16		KUMHO	6 mm
R/H Rear Tyre	205/55 R16		KUMHO	6 mm
L/H Rear Tyre	205/55 R16		KUMHO	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/11/2020		Inspection Date	02/12/2020
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	