



SERVICE REQUESTS

MESSAGES

CLAIMS



## Service Request Details

Claim

SOM02XSU

Reference

CS3/ASM20013194/Aqd3e2 

Loss Date

25 November 2020

Report Date

26 Nov 2020 12:12:00 PM

Request Date

1 December 2020

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

### Actions

Next Step

Wait for: Approve invoice

[Add Invoice](#)

### Vehicle Information

Incident Vehicle Registration #

SGV2007U

Make

TPVD

Model

SUZUKI GRAND BLACK

### Service Address

SLIP RD RIFFLE RANGE, , ,

### Primary Contact/Insured

KUM LIAN SEE SHARON

3 JALAN RAJAWALI, #06-04, 598436,  
Singapore

SHARONKUM@HOTMAIL.COM

Claim Handler

KHONG Lynn  
68804892

lynn.khong@axa.com.sg

Additional Instructions  
TP WS Garage 13 Pte Ltd

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

|               |                                                                                                                                |
|---------------|--------------------------------------------------------------------------------------------------------------------------------|
| NAME          |  <a href="#">ASM-LKKInvoice-AC2100667.pdf</a> |
| TYPE          | Invoice                                                                                                                        |
| SUB-TYPE      | Surveyor/ Assessor expense                                                                                                     |
| AUTHOR        | LKK AUTO CONSULTANTS PTE LTD (TP)                                                                                              |
| DATE UPLOADED | 3 February 2021                                                                                                                |

|          |                                                                                                                                |
|----------|--------------------------------------------------------------------------------------------------------------------------------|
| NAME     |  <a href="#">LKKPreRepairInspection.pdf</a> |
| TYPE     | Reports & Statement                                                                                                            |
| SUB-TYPE | Survey Report                                                                                                                  |

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 3 February 2021

---

NAME  [Resurvey Photo-2.pdf](#)

TYPE Evidence

SUB-TYPE Photos

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 3 February 2021

---

NAME  [Resurvey Photo-1.pdf](#)

TYPE Evidence

SUB-TYPE Photos

AUTHOR LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED 3 February 2021

---

NAME  [LKKPhoto.pdf](#)

TYPE Evidence

SUB-TYPE Photos

SUB-TYPE

PHOTOS

AUTHOR

LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED

3 February 2021

NAME

 [AXA Immediate Advice - SGV2007U \(PRS\).pdf](#)

TYPE

Reports &amp; Statement

SUB-TYPE

Others

AUTHOR

LKK AUTO CONSULTANTS PTE LTD (TP)

DATE UPLOADED

18 December 2020

NAME

 [GIA SGV2007U TP.pdf](#)

TYPE

Reports &amp; Statement

SUB-TYPE

GIA Report

AUTHOR

KHONG Lynn

DATE UPLOADED

30 November 2020

NAME

 [GA509202-Certificate of Insurance.pdf](#)

TYPE

Forms / Claim Documents

SUB-TYPE Policy Schedule / Covernote / Certificate of insurance

AUTHOR VISHNU BATHAM Shekhar

DATE UPLOADED 26 November 2020

---

NAME  [GA509202-Policy Schedule.pdf](#)

TYPE Forms / Claim Documents

SUB-TYPE Policy Schedule / Covernote / Certificate of insurance

AUTHOR VISHNU BATHAM Shekhar

DATE UPLOADED 26 November 2020

---

NAME  [GIA SKV1933E INSD.pdf](#)

TYPE Reports & Statement

SUB-TYPE GIA Report

AUTHOR VISHNU BATHAM Shekhar

DATE UPLOADED 26 November 2020

---