

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.12.2020

REPAIR ESTIMATE

Time: 14:38:09

Page: 1

China Taiping
CP/P

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305436691
REGN NO : SHB2369T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 09.10.2019
DATE/TIME IN : 28.11.2020 11:55
ACCIDENT DATE : 27.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-9999-2024-A REAR DOOR APPS STICKER RH 1 80.00 0.00 80.00

SUB-TOTAL : 80.00

JOB NATURE

0000 PB PANEL BEATING-Rear Fender RH 350.00

0001 SP SPRAYPAINT CHARGE 500.00

0002 20-00 TUFF COAT ON AFFECTED PARTS. 40.00

SUB-TOTAL : 890.00

TOTAL : 970.00

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE :

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jie 97495747
WP' 01/12/20 09:00
2 days
1/P Repair after repair
Tan Jie C/Chantoon

750
80
830 #
2 days