

ASSIGNMENT

CUB Jan 2025

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 1107U Yr Regn: Jan/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai I40 c.c 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Reading: 293311 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU700723

C/No: KMHLB41UMHU097750

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 27/11/2020 D.O.I. 02/12/2020

Survey held at Bj Frost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Portion

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>China Taping TP 2567M.</u>

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

2) _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
S+RS SI	_____
Photos	_____
Others	_____
TOTAL	_____

Phone Number:

Fax Number:

Customer:		Date:	3/12/2020 10:00 AM
Company:		VIN	
License NO:	SHA1107U	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

HYUNDAI, i40 G 1.6 GDI, 11-11 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°34'	4°12'	5°12'	3°24' *
		Right	4°32'	4°12'	5°12'	4°34'
	Camber	Left	-0°58'	-1°00'	0°00'	-4°00' *
		Right	0°05' *	-1°00'	0°00'	0°16' *
	Toe	Left	-0°11' *	0°00'	0°12'	-0°22' *
		Right	0°02'	0°00'	0°12'	0°01'
Total		-0°09' *	0°00'	0°24'	-0°21' *	
Rear	Camber	Left	-1°42' *	-1°30'	-0°30'	-1°39' *
		Right	-2°11' *	-1°30'	-0°30'	-2°10' *
	Toe	Left	0°09'	-0°03'	0°09'	0°16' *
		Right	0°01'	-0°03'	0°09'	-0°07' *
		Total	0°10'	-0°06'	0°18'	0°09'
	Thrust Angle		-0°04'	99°59'		-0°11'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		10°20' *	13°18'	14°18'	10°20' *
	Right		8°21' *	13°18'	14°18'	8°21' *
Included Angle	Left		9°22' *	99°59'	99°59'	6°20' *
	Right		8°26' *	99°59'	99°59'	8°37' *
Toe Out On Turns	Left		----	99°59'	99°59'	----
	Right		----	99°59'	99°59'	----
Max Turn Inside	Left		----	99°59'	99°59'	----
	Right		----	99°59'	99°59'	----
Toe Curve Change	Left		----	0°00'	199°59'	----
	Right		----	0°00'	199°59'	----
Setback	Front		-0.03" *	99.99"	99.99"	-0.03" *
	Rear		-0.25" *	99.99"	99.99"	-0.25" *
Track Width Diff.			-0.03"			-0.03"
Wheel Base Diff.			0.22"			0.22"
Front Ride Height	Left		----	99.99"	99.99"	----
	Right		----	99.99"	99.99"	----
Rear Ride Height	Left		----	99.99"	99.99"	----
	Right		----	99.99"	99.99"	----
Frame Angle						----