

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305436698
Date : 01/12/2020
Time of Fax: _____

Via Fax : Email/162962706
Your Insured: GBF 9237U
Date of Acc : 28/11/2020

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

A 2554E

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

♦ Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} Fax no. 6546 8156
♦ Juman Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
♦ Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

for Vice President
Crash Repairs & Claims Recovery

LONPAC

1/2 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305436698
REGN NO : SHA2554E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 30.11.2020 12:40
ACCIDENT DATE : 28.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0595-G	REAR DOOR RH	1	2,201.10	20.00	1,760.88
0002 28-01-9999-2023-A	REAR DOOR APPS STICKER RH	1	80.00	2.00	80.00
0003 04-01-0103-0658-G	REAR WHEEL CAP RH	1	217.20	20.00	173.76

SUB-TOTAL : 2,014.64

JOB NATURE

0000 20-05	Rear Door Adv.Sticker RH	100.00
0001 20-05	Rear Fender Adv.Sticker RH	100.00
0002 PB	PANEL BEATING-Rear Fender RH	600.00
0003 SP	SPRAYPAINT CHARGE	750.00
0004 20-00	TUFF COAT ON AFFECTED PARTS.	100.00
0005 L	TRANSFER OF DOOR	120.00

SUB-TOTAL : 1,770.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 01.12.2020

REPAIR ESTIMATE

LON PAT

Time: 16:03:55

Page: 2

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305436698
REGN NO : SHA2554E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 29.12.2016
DATE/TIME IN : 30.11.2020 12:4
ACCIDENT DATE : 28.11.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,784.64

Lmfs

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :