

Our Job Ref No : 305436677

Date : 03/12/20

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156

FINA	LIZATI	ON FORM					
То	:LKK				Fax:		
Attn	<u></u>	TAUFIKH					
Vehicle Reg No. : SHA5496U			Dat	e of Accident	:29-Nov-20		
The s	survey a	and estimates o	f the repairs of the ab	ove-mentione	d vehicle are	as follows:-	
The repair job shall bill to:			ill to:	NTUC		GBD7941T	
2.	The finalized amount shall be:						
۷.							
	(a)	•	ter List discount				
	(b) Labour Charges					£	
	Total for Part-By-Part Repair Cost						
	(c.)	Lumpsum Rep	air (if applicable)				
	Total for Lumpsum repair cost after Less: 20%					\$450.00 \$450.00	
	Final Lumpsum Repair cost						
3.	3. Estimated normal period for repairs: 2 working days.						
4.	We sh	iall treat the ab 7 working day	ove amount as Corr ⁄s	ect and Conf	irmed if there	is no reply from you	
5. Thank you for your assistance. We confirm the estimate						estimates and	
9.0	Thank you for your assistance.				finalized amount		
			0				
	UMIS					1- 1.//	
	Signat	-		- Sig	gnature	taufikh	
	Name : LIMTS			Name		TAUFIKH	
	Tel :621483		62148398	_ Date :		8/12/20	
	Fax	:	65468156	•			
For O	fficial l	Jse Only					
				Document	0 " "		
	ŀ	tem	Amount	Attached	Confirm By (Signature)	Remarks	
Rental Rate P/Day		to P/Day		Yes or No YES			
Loss of Income Paid				NO NO			
3. Survey Fees				140			
4. LTA Search Fee			\$7.49 / \$2.00			4.	
5. Medical Fees (on behalf			711117 92100				
5. Me			i i				
5. Me of c		applicable)					