

Our Job Ref No : 305436765Date : 04/12/20ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : TAUFIKHVehicle Reg No. : SH6349M01/12/20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: NTUC GBB7908B
2. The finalized amount shall be:
- |   |                   |
|---|-------------------|
| (a) Spare Parts after List discount       | <u>\$590.10</u>   |
| (b) Labour Charges                        | <u>\$550.00</u>   |
| <b>Total for Part-By-Part Repair Cost</b> | <u>\$1,140.10</u> |
| (c) Lumpsum Repair (if applicable)        |                   |
| Total for Lumpsum repair cost after Less: |                   |
| <b>Final Lumpsum Repair cost</b>          |                   |

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and  
finalized amountSignature : Name : CHIANGTel : 62148314Fax : 65468156Signature : taufikhName : TaufikhDate : 8/12/20**For Official Use Only**

| Item  | Amount        | Document Attached<br>Yes or No | Confirm By<br>(Signature) | Remarks |
|---|---------------|--------------------------------|---------------------------|---------|
| 1. Rental Rate P/Day                                    |               | YES                            |                           |         |
| 2. Loss of Income Paid                                  |               | N                              |                           |         |
| 3. Survey Fees  |               |                                |                           |         |
| 4. LTA Search Fee                                       | \$7.49/\$2.00 |                                |                           |         |
| 5. Medical Fees (on behalf<br>of driver, if applicable) |               |                                |                           |         |
| 6. Overrun  |               |                                |                           |         |

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305436765  
REGN NO : SH 6349M  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 14.11.2019  
DATE/TIME IN : 01.12.2020 16:05  
ACCIDENT DATE : 01.12.2020

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|                        |                           |      |        |       |        |
|------------------------|---------------------------|------|--------|-------|--------|
| 0001 04-01-0104-2533-G | IONIQV2-4 MOULDING ASSY-R | 1    | 451.25 | 20.00 | 361.00 |
| 0002 04-01-0101-0111-G | HYUNDAI BUMPER COVER CLIP | 10 L | 22.00  | 20.00 | 17.60  |
| 0003 09-01-9999-0068-A | HYUNDAI REVERSE SENSOR AS | 1    | 180.00 | 10.00 | 162.00 |
| 0004 FNPS              | NO PLATE(S)               | 1 N  | 55.00  | 10.00 | 49.50  |

SUB-TOTAL : 590.10

## JOB NATURE

|            |                             |        |
|------------|-----------------------------|--------|
| 0000 PB    | PANEL BEATING               | 320.00 |
| 0001 SP    | SPRAYPAINT CHARGE           | 200.00 |
| 0002 20-22 | REMOVE/REFIX REVERSE SENSOR | 30.00  |

SUB-TOTAL : 550.00

TOTAL : 1,140.10

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :