


National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTU	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC20013307/Ntf3e2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	11-12-2020 INC4		
1.	. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBE 6606M	Veh. Inspected SHB 3112K		SHB 3112K	
	Policy No.	5077735940-04	Cover	age (\$)	0.00	
	Claim No.	MT/1112068-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	02/12/2020	
2.	Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	of Reg.	2019	
	Chassis No.	KMHC851CVKU140364	Colou	r	YELLOW	
	Odometer	236205	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
4.	Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	01/12/2020	Inspec	ction Date	02/12/2020	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					