

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

NRMC-PP

Date: 02.12.2020
Time: 13:40:54
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305436769
REGN NO : SHB3112K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 02.04.2019
DATE/TIME IN : 02.12.2020 08:05
ACCIDENT DATE : 01.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G IONIQV2&3 COVER-FR BUMPER 1 430.90 20.00 344.72 / CRK
0002 04-01-0104-2915-G IONIQV1-3 LAMP ASSY-HEAD 1 1,993.65 20.00 1,594.92 / SCR

SUB-TOTAL : 1,939.64

JOB NATURE

0000 PB PANEL BEATING 400.00 320
0001 SP SPRAYPAINT CHARGE 300.00 200
0002 17-01 CHECK ALL LIGHTING 50.00 20

SUB-TOTAL : 750.00

TOTAL : 2,689.64

MVA NAME & SIGNATURE

DATE : 2/12/20

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

NAZ LKK

2/12/2020 1600

PIP

2 DAY

BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: