

ASS. REC. BY:

Steve

REF:

A16

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMR 583K

Yr Regn:

17/12/19

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c 1591

Colour:

Red

A/C: Insured / Std / NI / N

Sp. Reading

13158

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNA F5416 ML 5257798

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Nexen

Front

Rear

R/Bal.

mm

R/Bal.

L/Bal.

mm

L/Bal.

D.O.A.

2/12/20

D.O.I.

3/12/20

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MR-84K

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

\$ + RS. \$

Photos

Others

TOTAL

Rep. Form:

Lump Sum / L.B. /



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11690/SURIAH BINTE SELAMAT Reg No/Reg Date SMR583K / 17/12/201 Date In/Mileage / 0 Chassis No KNAF5416ML5057708 Engine No G4FGKH751124 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	03/12/2020/ 13:55	QUK	282 / Kevin Leong	25202

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, FRT RH FENDER & AFFECTED AREA				800 1200.00
E PNT98000 PAINT WORK ON FRT BUMPER & FRT RH FENDER 480 y2				960.00
E PNT88000 REMOVE & INSTALL FRONT PARKING ASSIST				120.00
M SUNDRY PERFORM RUST PREVENTION				40.00
A 54900099 CHECK CHASSIS & WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREA				160.00
M SUNDRY SUNDRIES				20 50.00
M LAMP ASSY-HEAD,RH	1.00	2210.00	20.00	1768.00
M PANEL-FENDER,RH	1.00	430.00	20.00	344.00
M COVER-FR BUMPER	1.00	633.00	20.00	506.40
M GRILLE ASSY-RADIATOR	1.00	328.00	20.00	262.40
M GRILLE-FRONT BUMPER	4.00	485.00	20.00	1552.00
M MOULDING-FRONT BUMPER,RH	1.00	216.00	20.00	172.80
M LAMP ASSY-SIDE REPEATER,RH	1.00	143.00	20.00	114.40
M ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20
M AIR DUCT-FR BUMPER,RH	1.00	14.00	20.00	11.20
M BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60
M ULTRASONIC SENSOR ASSY-P.A.S	1.00	163.00	20.00	130.40
M GUARD ASSY-FRONT WHEEL,RH	1.00	95.00	20.00	76.00
M ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60

Estimate

3/12/20, 4.00pm

Steve (LKK)

OD - Not Auth
EXCESS - ?

P/P

By R/L SM
4 days

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Authorized signatory and company stamp

Third party survey is on a 'without prejudice' basis

Nett	7,728.00
7% GST on	7728.00
Total Payable	8,268.96

Valid for 14 days from date of quote. This is a computer generated document, no signature is required.
 Es... are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
 any additional parts or labour that may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
 after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a
 deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or
 cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing
 the rubber seal or other repair requiring the removal of the windscreen.

Date: