

Sonuçlar :

Special Instruction:

L/Sum: \$ 10476.40

Third Parties:

Claimant:

Surveyor:

Workshop: Green Star Spray Painting

To Inspect Vehicle No: SGN 3408E Insured: GBJ 4438K
at Workshop m/s Green Star Spray Painting Tel: 65463092
of Blk 3011 Bedok North Ave 4 #01-2004 Bedok Industrial Park E

Insured: GBJ 7425K

at Workshop m/s green star spray painting Tel: 65463092
of Blk 301 Bedok North Ave 4 #01-2004 Bedok Industrial Park E

Tel: 65463092

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 22-08-2020

(Client's Record) Re-Inspection : ~~16-Dec-2020 10:00 AM~~
21-01-21 9.00A.M

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original! _____ days)

Date/Time: _____ Submit Final Fig _____, ____ days (Red \$ _____ / ____ %; Original ____ days)

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add

Transport

Photos

Others

Total

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____