

Tow
Car In

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

30 NOV 2020

ESTIMATE

Estimate No. : b1 56698
Date Estimated : 30/11/2020
Prepared By : Chua Kee Sin

Page No. : 1 of 7

- ESTIMATE REPAIR FOR -
Tan Teck Ching (Chen Dixin)
311C Clementi Avenue 4
#14-191
Singapore 123311

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H46190	28/04/2017	216d G TOURER	0

DESCRIPTION

Rear rear floor pan, tail end panel, boot lid, rear bumper
include removing attachment et c and repair on the accident
damage area

6800 / 9,350.00

(2) Spray painting rear floor pan, tail end panel, both rear side
fender, rear boot lid and rear bumper

4470 / 4,987.00

To replace rear windscreen gla ss.

676.00

To conduct water leak tests.

75.00

To supply and install rear windscreen solar film.

Xm 531.00

To check electrical wiring sys tem and lighting at the rear s
ection for proper function.

150 / 177.00

To replace rear exhaust silenc er including alignment system
and conduct check for leak.

451 / 531.00

To carry out body cavitypreser vation. (For cut panel).

451 / 531.00

To carry out body cavitypreser vation. (Per panel).

100 / 118.00

To replace front centre exhaus t silencer including alignment
and conduct checks for leak.

451 / 531.00

To remove and install boot com partment carpet and garnish to
facilitate repair.

230 / 271.00

To tow accident vehicle to PML workshop.

150.00

Being charge for LTA inspection fees.of breaking
amd install no plate seal

? / 160.00

Sundries

? / 150.00

NEC

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 56698
Date Estimated : 30/11/2020
Prepared By : Chua Kee Sin

Page No. : 2 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H46190	28/04/2017	216d G TOURER	0

DESCRIPTION

To supply rear emboss number plate - Red ~~red~~

VALUE

Xnn 83.00

Total Labour 1: 18,301.00

DESCRIPTION

QTY

PRIC

VALUE

C CLIP FOR PLASTIC NUT ? Xnn	10	1.10	11.00
RUBBER MOUNTING ? Xnn	2	17.70	35.40
FRONT SILENCER ? bt/	1	1,020.75	1025.85 / 1,020.75
REAR SILENCER ? bt/	1	1,010.00	1015.05 / 1,010.00
TAILPIPE TRIM BLACK CHROME SCRX NN	1	112.20	112.20
HOLDER EXHAUST SYSTEM ? ne	2	58.65 2875	28.75 / 117.30
BOOTLID ?	1	1,210.35	1174.04 / 1,210.35
LH TRUNK LID HINGE ? xsul	1	79.75	79.75
RH TRUNK LID HINGE ? xsul	1	79.75	79.75
TRUNK FLOOR ?	1	581.30	530.55 / 581.30
INTERIOR TAIL TRIM ? de	1	280.50	280.50
TAIL PANEL ?	1	357.00	357.00
REPAIR KIT GROUND STRAP ? Xnn	1	30.65	30.65
RR BUMPER LH SIDE GUIDE ? xsul	1	61.35	61.35
RR BUMPER RH SIDE GUIDE ? xsul	1	61.35	61.35
REAR BUMPER CARRIER ?	1	460.40	446.59 / 460.40
SUPPORT ? ca/	1	45.55	45.55
RR BUMPER LH INNER SIDE GUIDE ? ca/	1	61.35	61.35
RR BUMPER RH INNER SIDE GUIDE ? ca/	1	61.35	61.35
REAR BUMPER TRIM STRIP (CHROM) ? ca/	1	110.55	110.55
LEFT PROTECT ? Xnn	1	11.20	11.20
RIGHT PROTEC ? Xnn	1	11.20	11.20
REAR BUMPER PANEL PRIMED (LINES PDC de	1	1,045.45	1,045.45
SET MOUNTS PDC SENSOR REAR ne Xnn	1	60.70	60.70
REAR BUMPER TOWING FLAP EYE PRIMED SCX xsul	1	43.05	43.05
LETTERING 216 D ne	1	64.45	64.45
GROMMET ne	2	0.80	1.60
PLAQUE 74MM ne	1	71.60	71.60
STRIKER BOOT LID ? xsul	1	59.80	59.80
LOCK TRUNK LID ? xsul	1	194.75	194.75
ACTUATION UNIT ? xsul	1	612.10	612.10
SPINDLE DRIVE - rear boot ? xsul	2	355.65	711.30
Lock plate ? xsul	1	12.40	12.40
BUMP STOP ? Xnn	10	3.20	32.00
REAR WINDOW ? xsul	1	657.60	657.60
HOOK AND LOOP FASTENER ? Xnn	4	2.85	11.40
LH UPHOLSTERY 3RD ROW SUPPORT ? Xnn	1	23.55	23.55
RH UPHOLSTERY 3RD ROW SUPPORT ? Xnn	1	23.55	23.55
3rd ROW LUGGAGE COMPARTMENT TRAY ? SCX	1	126.90	126.90
Bodenverklei- floor trim 3tow ? xsul	1	916.10	916.10
THERMAL PROTECTION LUGGAGE COMP. WE ✓ NEC	1	58.30	58.30
LOADING SILL COVER (ANTHRAZIT) ? de	1	79.55	79.55
LOADING SILL COVER (ANTHRAZIT) ? Xnn	1	79.55	79.55

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 56698
Date Estimated : 30/11/2020
Prepared By : Chua Kee Sin

Page No. : 3 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H46190	28/04/2017	216d G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
rear floor trim - rear seat ? X svl	1	916.10	916.10
REAR BUMPER HEAT INSULATION ? X svl	1	63.50	63.50
TRIM PANEL TAILGATE BOTTOM INNER (S ? X svl	1	282.65	282.65
WARNING SIGNALLER ? X svl	1	35.35	35.35
BOOTLID SEALING X svl	1	143.85	143.85
REAR LH REFLECTOR ? X svl	1	38.85	38.85
REAR RH REFLECTOR ch ✓	1	38.85	38.85 ✓
LH GUTTER STRIP ? X svl	1	25.95	25.95
RH GUTTER STRIP ? X svl	1	25.95	25.95
REAR LH LIGHT IN THE TRUNK LID ? X svl	1	262.15	262.15
REAR RH LIGHT IN THE TRUNK LID ? X svl	1	262.15	262.15
REAR LH LIGHT IN THE SIDE PANEL ? X svl	1	374.45	374.45
REAR RH LIGHT IN THE SIDE PANEL ? X svl	1	374.45	374.45
NUMBER-PLATE LIGHT LED ? X svl	2	27.45	54.90
DECOUPING RING PDC TORQUE CONVERTER ? X svl	4	5.10	20.40
ULTRASONIC SENSOR IMPERIALBLAU(WA89 ? X svl	4	370.00	1,480.00
SET ADHESIVE PADS FOR ACE 2.0 nn Xnn	1	43.65	43.65
BLIND RIVET AVIBVLB ? nn	43	0.55	23.65
BLIND RIVET AVIBVLB ? nn	23	0.55	12.65
BLIND RIVET AVIBVLB ? nn NEC	20	0.55	11.00 ✓
SCREW (SF PLUS M5X15) ? nn Xnn	11	0.55	6.05
SCREW (SF PLUS M5X15) ? nn	5	0.55	2.75
SCREW (SF PLUS M5X15) ? nn	3	0.55	1.65 ✓
(DG/SL) BODY ADHESIVE K5B (195ML) nn ✓	1	331.80	331.80 ✓
(DG/SL) BODY ADHESIVE K5B (195ML) nn Xnn	1	331.80	331.80
(DG) BODYWORK ADHESIVE K5A (50ML) nn ✓	1	114.45	114.45 ✓
(DG) BODYWORK ADHESIVE K5A (50ML) nn Xnn	1	114.45	114.45
(DG) CLEANER R1 (100ML) nn ✓	1	26.15	26.15 ✓
(DG) CLEANER R1 (100ML) nn ✓	1	26.15	26.15 ✓
(DG) CLEANER R1 (100ML) nn Xnn	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) nn ✓	2	131.55	263.10 ✓
PUNCH RIVET N4 nn ✓	23	0.55	12.65 ✓
PUNCH RIVET N4 nn Xnn	19	0.55	10.45 ✓
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) nn ✓	1	27.85	27.85 ✓
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) nn Xnn	1	27.85	27.85
(S/L) SEAM SEAL 300ML nn ✓	1	33.80	33.80 ✓

Total Parts : 16,543.55

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 56698
Date Estimated : 30/11/2020
Prepared By : Chua Kee Sin

Page No. : 4 of 7

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN2953X	WBA2E320605H46190	28/04/2017	216d G TOURER	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 01/12/2020 @ 1120 Excess S\$ _____

Surveyor's Name Rajan Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 15 days



Labour 1	:	18,301.00
Parts	:	16,543.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,439.12
Grand Total	:	37,283.67

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **