





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/01/2021

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1605J
Case Reference Number	BUS/11/20/5056
Registration Date	28/1/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Low Kuang Leng
Type of Accident	Side Swipe
Accident Date and Time	30/11/2020 3:00 PM
Accident Reported Date and Time	30/11/2020 4:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109044
Special Instruction to ARC,if any	SMB1605J-FRONT WINDSCREEN CRACKED AND RIGHT VIEW MIRROR DAMAGED YQ1634D (TP) INSURED WITH ERGO
Prepared Date and Time	2/12/2020 4:53 PM
Chassis Number	WMAA22ZZ3F7002582
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,325.00
Total Spray Cost	\$878.00	\$708.00
Total Spare Part Cost	\$4,971.22	\$4,971.22
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$7,439.22	\$7,004.22
Lump Sum Total	\$0.00	\$7,000.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	02/12/2020 5:00 PM	04/12/2020 3:34 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/01/2021

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00				\$1,325.00 ✓		
Total Labour			\$1,590.00				\$1,325.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TO PUTTY & RESPRAY			\$878.00				\$708.00 ✓		
Total Spray Painting & Panel Beating			\$878.00				\$708.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			IU BRACKET	1.00	\$35.00	0.00	\$35.00	Replace	Replace ✓NEC
6010148	GLASS	4001X01-GLASS5171	WINDSCREEN,FRONT:F OR MAN A22 BUS	1.00	\$5,031.80	10.00	\$4,528.62	Replace	Replace ✓BR
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace ✓NEC
4006314	CONSUMABLE		ADHESIVE:DIRECT GLAZING	10.00	\$37.00	0.00	\$370.00	Replace	Replace ✓NEC
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace ✓NEC
6010161	BODY RH	4001M01-ACCE467	MIRROR,VIEW:FRONT,R H,FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	Replace ✓CR4
Total					\$6,508.70		\$6,214.03		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

6,214.03
- 2040
4,971.22
1,325
708
7,004.22

L15
\$7,000
3 days