

CS3/LPC20001323/Qvd3-1

22/03/2020

ASS. REC. BY:

REF

~~CS3/LPC20001323/Qvd3-1~~

Special Instruction:

Surveyor: Shin Pin

ASSIGNMENT (Office)

03/12/2020

From (Person): Org Hi Li

of

JPC

Date/Time:

03/12/2020 @ 12:16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G8B 9329J

Insured:

YP5154B

at Workshop m/s

Eng soon painting

Tel:

6760 6271

of

Blk 4 Yew Tee Ind. Est 393-J woodlands Road

Policy No:

Claim No:

19/20/20/VCOO/022944

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/01/2020

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

12:40pm @ 22/1/2020

Person Contacted:

Mr. Teo

Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Estimate (X)</u>
	<u>G8B 9329J-X</u>
	<u>YP5154B-CC4/LPC19019267/Fh93n2</u>
	<u>DoA: 23/10/2019</u>
<u>10/2/20</u>	<u>Submit PRS</u>
<u>14/12/20</u>	<u>Submit LS \$2600 (Red 4700, 64%)</u>

ASS. REC. BY: Sun Pin

REF: LFC

ASSIGNMENT

CoE Exp: 08/03/2024

PRS

From:

Date:

4/02/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBE 9329J

at Workshop m/s

Eng Soon Painting

of

BLK 4 yew tee Ind. est 393-J

Insured:

woodlands Road

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Vehicle In

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBB 9329J

Yr Regn: 09/03/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Pyna 150

c.c 2986

Colour

Blue.

A/C:

Insured / Std / NI / NA

Sp. Reading

732619

T/Radio:

Insured / Std / NI / NA

Eng/No:

-

C/No:

JTFAT35Y30K200393.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

195 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

21/01/2020

D.O.I.

4/2/2020

Survey held at

Eng Soon.

04/20/20

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV = 20,000

PV = 10,906

NV = 9,094.

RECEIVED 10 FEB 2020

Repair Range.
2.5k - 3k.

Repair day: 3 days

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 10/2 - typist

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

120

Transportation:

S + RS. \$

Photos

Others

TOTAL

120

Report Format:

Lump Sum / LBT: \$

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)