



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013356/Utd3e2	
			Date: 04/01/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 1272Z		Veh. Inspected	YL 7733M
Policy No.			Coverage (\$)	0.00
Claim No.	CMTD2003515/MYE		Excess (\$)	0.00
Assign From	MELVIN YE YONG KANG		Assign Date	04/12/2020
2. Vehicle Particulars & Condition				
Make & Model	ISUZU NPR71(A)		c.c	4570
Engine No.	HIDDEN		Year of Reg.	2004
Chassis No.	JAANPR71L47101591		Colour	WHITE
Odometer	534877 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		7.00-16	HEADWAY	5 mm
L/H Front Tyre		7.00-16	HEADWAY	5 mm
R/H Rear Tyre		185 R14 (D)	FALKEN	5/5 mm
L/H Rear Tyre		185 R14 (D)	FALKEN	5/5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/12/2020		Inspection Date	04/12/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	