

ASS. REC. BY:

REF:

CS3/AH20013426/R19f3

8/6A

PRS

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCF926Lat Workshop m/s V-TECH AUTOof 1,800W LEST #06-04Insured: AlhPolicy No. 1900102434Claims No. 5355569326SG

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 61K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SCF926L Yr Regn: 2000 / PRBType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MINIBUSHA DITRAKE 1.2CVT c.c. 1193Colour: MARON A/C: Insured / Std / NI / NASp. Reading: 010 765 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: M.M.BSTA/BAKH 002575

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R15

R: _____

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or -

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 02/12/2020 D.O.I. 07/12/2020Survey held at V-TECH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Submit DAR; 5 repair days.

Date/Time, File Pass to?



Prelt. Report

1) 09/12 Typist



Final Report

Date/Time, File Return to?

2)

Report Format: MER-DAR

Lump Sum / L.S.R. (\$) _____

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee:



Site Insp

(\$



Interview

(\$



Tech. Invs

(\$



Weekend

(\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Date of Submission	03/12/2020 19:04 (SGT)
Date of Accident	02/12/2020 19:50 (SGT)
Exact Location of Accident	283 Choa Chu Kang Ave 3, Singapore 680283
Additional Location Information	BLK 283 CHOA CHU KANG AVE 3 OPEN CAR PARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCF926L

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ONG LIANG MANG
NRIC No	SXXXX816A
Email Address	ong.lm56@gmail.com
Mobile Phone No	(Phone) +65-96659610
Alternative Phone No	+65-96659610

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070013958
Cover Note Number	-

DRIVER

Name of Driver	ONG LIANG MANG
NRIC No	SXXXX816A
Date Of Birth	06/06/1956
Occupation	Indoor

Date Of Driving Pass	03/08/1976
Driving experience	44 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96659610
Alt. Phone Number	+65-96659610
Email Address	ong.lm56@gmail.com
Address	BLK 283 CHOA CHU KANG AVE 3 #08-416
Address complement	-
Postcode	680238
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Parked Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No	Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident	2	Number of vehicles involved in the accident
Was anybody injured in the Accident?	No	Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?	-	Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?	Yes	Was any other material or property damaged?
Number of Passengers (Including Driver)	1	Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No	Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No	Was the accident reported to the police?
Was notice of intended Prosecution given?	No	Was notice of intended Prosecution given?
If yes, against whom?	-	If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

KINDLY REFER TO SKETCH PLAN.	KINDLY REFER TO SKETCH PLAN.
------------------------------	------------------------------

ATTACHMENT(S)

Are accident photos available for attachment?	Yes	Are accident photos available for attachment?
Was there any video captured by Car Camera?	No	Was there any video captured by Car Camera?
Was there any audio recorded?	No	Was there any audio recorded?

DETAILS OF OTHER VEHICLE INVOLVED

Vehicle Registration Number	SML5937Y
Vehicle Manufacturer	Toyota
Vehicle Model	Prius
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	ZHANG YANQIANG
NRIC No	SXXXX025H
Contact Number	(Phone) +65-90121169
Address	-
Address complement	-
Postcode	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have Insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have Insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 3/12/20
11am

Driver's Signature
(If driver is not the policyholder)
Date & Time: 3/12/20
11am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/ACC SketchPlan Form V1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

2/12/2020 7pm I parked my car at B/K 283 Choa Chu Kang Ave 3 open car park.

Today morning 3/12/2020 7.55am, When I collecting my car. I was shocked car was bang. Found there is a notes on my windscreen. I contact the number and file report for claim repair

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.


- Reporting Only
- Claim OD
- Claim TP
- Claim OD (TP) at other workshop


✓


DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Vtech Auto Service


 Policyholder's signature
 Date & Time 3/12/20
 11am


 Driver's Signature
 (If driver not the policyholder)
 Date & Time 3/12/20
 11am


 Reporting Centre Personnel's Signature
 Name:
 Nric/Fin No.

(1) Damaged (2) Dented (3) Dented (4) Cracked (5) Cut (6) Scratched (7) Deformed
(8) Buckled (9) Broken (10) Broken (11) Necessary (12) Missing (13) Torn
(14) Confirmed (15) Not Working

MOTOR CAR (Frt)

SCF 926L

ACTION (AC)
(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug 2005

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	di	/	
1005	992341	Frt Bumper Clips	na	/	
1006	991325	Frt Bumper Bracket	na	/	
1007	991462	Frt Bumper Side Retainer	na	/	
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler	ca	/	
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	scf	/	
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	ca	/	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	scf	R	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	bt	/	
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Accessories:

ORIGINAL COPY

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	816A

Vehicle No.:	SCF926L
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Dec 2020
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	3A92UHX7207
Chassis No.:	MMB5TA13AKH002575
Maximum Power Output:	59.0 kW (79 bhp)
Open Market Value:	\$13,809.00
Original Registration Date:	18 Feb 2020
First Registration Date:	18 Feb 2020
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Feb 2030
PARF Rebate Amount:	\$3,750.00

COE Expiry Date:	17 Feb 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,010.00
COE Rebate Amount:	\$27,598.00
Total Rebate Amount:	\$31,348.00

The information contained herein is correct as at 07 Dec 2020

OK

Red

t.com/used_cars/info.php?ID=905184&DL=1000

Mitsubishi Attrage 1.2A

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$63,999		
Depreciation ⓘ	\$6,460 /yr View models with similar depre	Reg Date	16-Jun-2020 (9yrs 6mths 8days COE left)
Mileage	3,000 km	Transmission	Auto
Road Tax ⓘ	\$506 /yr	OMV ⓘ	\$14,697
Dereg Value ⓘ	\$33,481 as of today (change)	ARF ⓘ	\$5,000
COE ⓘ	\$31,210	Power	59.0 kW (79 bhp)
Engine Cap	1,193 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	N.A.		
Type of Vehicle	Mid-Sized Sedan		

Features

1.2L 3 Cylinder DOHC 12V MIVEC Engine, Immobilizer, Smooth INVECS-III CVT, ABS, EPS, 6 SRS Airbags, Keyless Entry, Cruise/Traction Control, ECO Mode. View specs of the Mitsubishi Attrage (2014)

Accessories

Full Original Bodykit, Leather Seats, Sport Rims, Bridgestone Performance Tyre S001, Rike Cool Solar Film With 10 Years Warranty JVC Touchscreen DVD.

