

ASS. REC. BY: From

REF:

CC3/AH 20013470/Ribs3


432F

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SGN 980P
at Workshop m/s PERFORMANCE
of 203, MEXXOLA RD
Insured: ALL
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 116k
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGN 980P Yr Regn: 2014 / PEB
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 730Li AT / 01/11/SP c.c 2996Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 128309 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NBAYE22010D221047

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50R18
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 04/12/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P = \$9,093.55

CHECK ITEM = \$701.70

R = \$1,853.70 / 83.07%

Date/Time, File Pass to?



: Prel. Report



: Final Report

1) _____
Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.H. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 432F

Vehicle No.: SGN980P

Vehicle to be Exported: No

Intended Deregistration Date: 08 Dec 2020

Vehicle Make: B.M.W.

Vehicle Model: 730LI AT D/AB 4DR SR LED DSC NAV HUD

Primary Colour: Grey

Manufacturing Year: 2013

Engine No.: 10B18508N52B30AF

Chassis No.: WBAYE22010DZ21047

Maximum Power Output: 190.0 kW (254 bhp)

Open Market Value: \$80,119.00

Original Registration Date: 19 Feb 2014

First Registration Date: 19 Feb 2014

Transfer Count: 0

Actual ARF Paid: \$116,215.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 18 Feb 2024

PARF Rebate Amount: \$75,539.00

COE Expiry Date: 18 Feb 2024

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$75,300.00

COE Rebate Amount: \$24,061.00

Total Rebate Amount: \$99,600.00

The information contained herein is correct as at 08 Dec 2020

OK

Grey

► BMW 7 Series 730Li Sunroof

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

EURO PERFORMANCE ASIA PTE LTD

Your Consignment PartnerTM

Price **\$116,800**

Depreciation **\$18,250 /yr**
View models with similar depre

Reg Date **26-Feb-2014**
(3yrs 2mths 17days COE left)

Mileage **98,000 km (14.4k /yr)**

Manufactured **2013**

Road Tax **\$2,382 /yr**

Transmission **Auto**

Dereg Value **\$99,760 as of today (change)**

OMV **\$80,119**

COE **\$75,300**

ARF **\$116,215**

Engine Cap **2,996 cc**

Power **190.0 kW (254 bhp)**

Curb Weight **1,790 kg**

No. of Owners **2**

Type of Vehicle **Luxury Sedan**

Features

BMW Inline 6 3.0 Engine Mated To An 8 Speed Gearbox On An RWD With 4 Driving Modes. Adaptive LED Headlights. View specs of the BMW 7 Series

Compare

