

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/11/2020 15:56
Date Of Accident	23/11/2020 15:05
Exact Location Of Accident	KRANJI LOOP (BS: 49189 – AFT KRANJI ROAD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB1411B
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	1XXXXX292D
Email Address	BARC@SMRT.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAN
Model	NL320F (A22)-10.5 D ABS TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-20095488MFBP
Cover Note Number	

Driver

Name of Driver	ZHAO YING SHAN
NRIC No	GXXXX615R
Date Of Birth	03/04/1976
Occupation	OUTDOOR
Date Of Driving Pass	07/05/2019
Driving Experience	1 YEAR AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	6 ANG MO KIO STREET 62
Postcode	569140
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	5

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 23/11/2020 at 1505 hrs, I was driving SMB1411B, SVC 925. There were approximate 5 pax onboard. I was travelling approximate 10km/hr along Kranji Loop. As I approached BS: 49189 for pax activity, I started to slow my vehicle down and eventually stopped my vehicle at the bus stop when I suddenly heard a thud sound. I engaged my handbrakes and alighted my bus to check and realized TP left front vehicle collided with my rear right vehicle. There were no pax onboard injured. I exchanged particulars with TP before calling BOCC regarding this matter. BOCC requested me to proceed with my revenue service back to Choa Chu Kang Bus Interchange before reporting this matter to my supervisor at Choa Chu Kang.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING DOWNLOAD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL28P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation. *car hit bus*
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Signature

Driver's Signature
(If driver is not the policyholder)
Date & Time: 24/11/2020



Reporting Centre Personnel's Signature
Name:
NR/C/FIN No.:


SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT *Krauji Loop (RS: 49187 - After Krauji Road.)*

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time 24/11/2020


Reporting Officer's Signature
Name
NOC PIN No.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 30/11/2020

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB1411B
Case Reference Number	BUS/11/20/7025
Registration Date	6/1/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Zhao Yingshan
Type of Accident	Head to Rear
Accident Date and Time	23/11/2020 3:05 PM
Accident Reported Date and Time	23/11/2020 4:15 PM
Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	right rear portion <i>AIG</i>
Prepared Date and Time	29/11/2020 11:22 AM
Chassis Number	WMAA22ZZ1D7001993
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$1,048.00	\$0.00
Total Spare Part Cost	\$5,095.22	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$8,263.22	\$0.00
Lump Sum Total	\$8,250.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	29/11/2020 11:32 AM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 30/11/2020

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$2,120.00	1590
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,048.00	878
Total Spray Painting & Panel Beating	\$1,048.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010062	Body	F01001-CW273	COVER REAR TAIL LAMP,RH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	✓ CR4
010464	VM	S01001-CW002	BRACKET, ATTACHMENT FOR MAN A22 BUS	1.00	\$569.30	10.00	\$512.37	Replace	✓ R
009991	BODY RH	4000F06-ACCE4526	PANEL, SIDE R10, FOR MAN A22 BUS	1.00	\$192.70	10.00	\$173.43	Replace	✓ R
009992	BODY RH	A01001-CW564	PANEL, SIDE R11, FOR MAN A22 BUS	1.00	\$1,782.50	10.00	\$1,604.25	Replace	✓ R
010299	VE	88-25320-6008	LAMP, INDICATOR LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	?
010298	VE	88-25225-6039	LAMP, STOP LED (MAN BUS)	2.00	\$1,141.70	10.00	\$2,055.06	Replace	?
Total					\$5,935.00		\$6,369.03		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair dy - 4 days

L/S

After paint photo.

Sun Pin (Uda)

01/12/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB1411B
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2020
Vehicle Make:	MAN
Vehicle Model:	NL320F (A22)
Primary Colour:	Multicolor
Manufacturing Year:	2013
Engine No.:	50334921163484
Chassis No.:	WMAA22ZZ1D7001993
Maximum Power Output:	-
Open Market Value:	\$253,995.00
Original Registration Date:	06 Jan 2014
First Registration Date:	06 Jan 2014
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 04 Dec 2020

OK